BAY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Located In: Corner Code ## 5 E. 14 N. K-7 **Public Land Survey**R ____ __ R R . R ._. **Property Controlling** in Section _ R __ T 3. Miscellaneous _ T _ Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat _____ Private Claims _ Ronald C. Prevost June 22 95 . in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Post Set by John Mullett 1839 W Oak S.42°E. 30 L 24" 7" N.56°W. 28 L Elm LCRC, L1 P247, P.K. Nail, Goss 1972 LCRC, L2 P615, P.K. Nail, Hughes 1989 LCRC, L3, P88, 3/8" Rod in Mon. Box - Recorded in error, should have been M-7, Juras 1994 Recorded Survey - L1315 P746, Spicer Witness 1949 Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found P.K. Nail, Agrees with Spicer Witnesses of 1949, Set By Spicer 1954 Also Found P.K. Nail 0.5' W. & 0.32'N. Holding with P.K. Location of 1949 & 1954 Monument accepted as the best available evidence of the position of the original corner. APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 33 June 95 Michael MacDonald P.S. County Representative C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced P.K. with 5/8" X 24" Re-bar with 2 3/4" Bay Co. Brass Cap in Mon Box on 7-17-95 K-7 Ctr. Hyd. N.40"W. 43.30 NE cor, Blk. Foundation House S.45°W. 91.32 (91.32 Rec.) Ctr. M.H. Cover S.30°E. 20.76 S.50°E. Ctr. M.H. Cover 25.66 PREVOST 1" Iron Pipe S.45°W. 45.72 (45.72 Rec.) PROFESSIONA Nail in W. Face T. Pole S.25°W. 40.06 Signed by ... /

24612

Burveyor's Michigan License No. _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983