SURVEY & REMONUMENTATION

APR 2 6 1995

COMMISSION

Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Located In: Corner Code #1 (County) 15N _B 3E **Public Land Survey** Ī 15N _R 3E T Ī R Ţ R Property Controlling T in Section S T R Miscellaneous S Ţ R

R

S 1 .r. O) 2 : 14 2 : 14 2 : 43 2 : 43

99

Register of Deeds Stamp & File Number

003

Lot No Private Claims

Property in Sec

or corners in

Bay

, Recorded Plat

S

Craig W. McVean June 10 and 13 . in a field survey on . 19 o hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned illines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land lanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below

OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

C 12 Set Post - H. Parke -1831 Hemlock 18" S 58° W 18 Lks. W. Oak 22" N 25° E 11 Lks.

CPC Survey 1967 - found wood stake - set iron BCRC - J & A Road Plans - found 3/8" iron rad - 1970 LCRC - L. 1, P. 183 - set iron - 1972 - De La Mater Recorded Surveys - L. 762, P. 132 - 1975; L. 805, P. 372 - 1977 C 13 Set Post - H. Parke, 1831 Hemlock 7" N 14° W 11 L.ks. Beech 10" N 81° E 18 Lks.

Consumer Power Company Survey - 1967 - found wood stake remains with rocks - Set iron.

Recorded Surveys L. 766, P. 106 - 1975; L. 805, P. 372 -1977.

10

11

12

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C 12 Found bent 3/8" rebar - down 1' per LCRC, BCRC and CPC. Raised to surface with 3/8" rebar. No recorded witness found. Monument agrees with recorded distance S. and proportionally N & S per CPC survey. Monument accepted as the pest available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 6-23-94. OF MICHICAL

C 13 Standard Section Corner common to Section 31 & 32. T15N, R3E. Found 3/8" rebar per CPC survey. Found CPC witness as follows:

NW 82.53' (82.55 - CPC) to nail in N side U.P.

Monument in agreement with CPC distances E & W and proportional to C 12 and C 11. Agrees with recorded distance N. and recorded distance E. to C 1 - T14N - R3E. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 6-23-94.

Description of monument for corner and as essaying stablished to perpetuate locating the position of the corner:

CRAIG W.

McVean PROFESSIONAL

C 12 Replace 3/8" Rebars with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box.

N 60° E 29.39' to nail and tag in top S end 12" CMP.

S 35° W 66.35' to NE corner 6" x 6' I-beam of E. leg Sandy Ridge sign.

S 52° W 398.55' to NW corner House #2778

S 14° W 271.23' to nail and tag in E. side U.P.

S 20° E 371.16' to nail and tag in W side U.P.

S 10° E 392.07' to NE corner House #2765.

C 13 Replace 3/8" rebar with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box.

N 52° W 82.59' to nail and tag in S side U.P.

N 30° E 64.78' to pk and tag in top N end 48" CMP.

N 84° E 150.93' to nail and tag in S. side U.P.

S 64° W 287.74' to NW corner House #2481.

S 55° W 17.56' to pk and tag in top S end 48" CMP. East 80.58' (80.5' - R, 80.52 - GLO) to 3/8" rebar at C 1 - T14N -

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 4/33/94

Michael MacDonald P.S. County Representative

Date 10-6 94

urveyor's Michigan License No. 39088