SURVEY & REMONUMENTATION

APR 2 6 1995

Bay County Remonumentation

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

105 003

or corners in			Time requirement of Act 14, whole			
Bay County:			Locate	ed In:	Corner Code //	
i .	Public Land Survey		J.	5N _R 3E 5N _R 3E	D 13 E 13	
			ī	R		
			7	R	•	
)	Property Controlling	S	T	R		
	in Section	S	Ţ	R		
}.	Miscellaneous	S	1	R		

1 1 .E. CD CD ្ដេភ Register of Deeds Stamp & File Number

Lat No

Property in Sec

. Recorded Plat

Private Claims

Craig W. McVean

in a field survey on

June 10

94

19

to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned i lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land 4an agement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below.

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

D 13 Set Post - H. Parke - 1831. Ironwood 7" N 60° E 33 Lks. Hemlock 10" N 57° W 18 Lks.

C.P.Co. Survey - 1967 - Found wood stake remains - Set

Recorded Survey - L. 873, P. 62 - Found stone - set iron - 1979.

E 13 Set post - H. Parke - 1831. Elm 10" N 661/2° W 16 Lks. Hemlock 9" N 6° F 9 Lks

C.P.Co. Survey - 1967 - Found wood remains - set iron. BCRC Witness Book - Found 3/8" re-rod with witness - No date. Recorded Survey - L. 873, P. 62 - Found 1" pipe - 1979.

10 11

12 1.3

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D 13 - Standard 1/4 corner common to Section 32, T15N, R3E -Found bent 3/8" rebar per L. 873, P. 62. Found 8" diameter stone 0.8' below. Found recorded witness as follows: NE 123.0 (M, R & CPC) to face U.P. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 8-4-94.

> APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County 1:1:4/11 1451 Michael MacDonald P.S. **County Representative**

E 13 - Standard Section corner common to Section 32 and 33. T15N, R3E - Found capped 3/8" rebar at surface. Excavated and found 1-1/4" outer diameter fron pinch bottom pipe along side wood post remains with rocks on E and W side below 3/8" rebar. Found witness as follows: South 25.47' (25.6' - R, 28.0 CPC, 28.09 BCRC) face U.P. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 8-25-94.

> APPROVED LAND CORNER 11.711 Michael MacDonald P.S. County Representative

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D 13 Replace 3/8" rebar and stone with 2-3/4" Bay County Brass Cap on 5/8" x 24" rebar in mon box. S 42° W 169.22' to NE corner foundation pole barn. S 51° W 186.20' to NW corner foundation pole barn.

S 68° W 177.19' to NE corner foundation House #2291.

N. 67" W 257.73' to nail and tag in S. side U.P.

N 66° E 123.16' to nail and tag in S. side U.P.

East 84.50' (84.43'-R) to 5/8" rebar at D 1-T14N-R3E.

E 13 Replaced 3/8" rebar, pipe, stones and wood post with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box. N 23° E 40.10' to nail and tag in top W. end 36" CMP. N 68° E 80.50' to nail and tag in top E. end 36" CMP.

S 65° E 163.37' to nail and tag in top N. side U.P.

S 10° W 25.74' to nail and tag in top W. side II Break to OF MICHIGA OF MICHIGAN CRAIG W. MCVEAN PROFESSIONAL FORM APPROVED BY MICHIGAN STATE BOARD OF EMBELLA TABLE 28, 1971

REVISED JAN. 198: SURVEYOR

urveyor's Michigan License No. 39088