SURVEY & REMONUMENTATION

APR 2 6 1995

For comers in

RECORDED

COMMISSION

Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Hoy 21 3 48 PM '94

Located In: Corner Code ≠# County T.15N... R.3E... G_12 1. Public Land Survey T 15N R 3E _____ A T _____R __ 2. Property Controlling T ____ R in Section S T R .. ,. R S Ţ Miscellaneous R Property in Sec. S T

Diene What it where REGISTER OF BEEDS BAY COUNT .. HICHIGAN

109 003

Register of Deeds Stamp & File Number

Private Claims ...

I. Craig W. McVean .. in a field survey on June 10 and 13 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

> CRAIG W. McVEAN ROFESSIONAL SURVEYOR No.

Description of original monument and accessories and/or subsequent restoration:

G 12 Set 1/4 Section Post - H. Parke - 1831. Beech 8" N 68° E 29 Lks. Maple 14" S 47° W 12 Lks.

LCRC - L. 1, P. 209 - Found bent 3/8" rod - implace with 1/2" pipe - Whittier - 1972.

BCRC witness book - 12" pointed stone and 1" x 12" Wood Stake -No date.

Recorded Surveys - L. 676, P. 423 & 424 - 1972; L. 740, P. 346 - 1974; L. 834, P. 455 - 1978; L. 869, P. 925 - 1979; L. 1035, P. 497 - 1986; L. 1035, P. 520; L. 1035, P. 532 -1986; L. 1107, P. 747 - 1989.

G 13 Set Post - H. Parke - 1831. Sugar 9" N 57° E 26 Lks. Hemlock 8" N 46° W 23 Lks.

BCRC Witness Card - 1/2" x 2" Flat Iron - 1972. Recorded Surveys - L. 836, P. 875 - 1978; L. 842, P. 617 - 1978; L. 842, P. 618 - 1978; L. 1035, P. 520 - 1986; L. 1035, P. 535 - Found 3/4" pipe - 1986.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G 12 Found 1/2" internal diameter iron per LCRC and Recorded survey at East - West occupation line. Found recorded witness as

SW (-R) 101.90' (101.95' & 101.96'-R) to N. and shiner in W. side U.P

WSW (R) 82.55' (82.5-R) to centerline 12" Ash.

Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 8-4-94.

G 13 Standard corner common to Section 33 and 34, T15N. R3E - Found 3/4" outer diameter iron pipe with red brick collar per recorded surveys. In agreement with GLO closing distance to G 1 - T14N-R3E. Monument accepted as the best available evidence to the position of the original corner. Accepted by Bay Her Acc. County Peer Review Group on 8-4-94. OF MICHIGAN

39088

Description of monument for corner and accessories established to perpetuate locating the position of the Capiession

G 12 Replace 1/2" pipe with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box.

East 28.15' to nail and tag in wood post.

N 30° E 56.10' to capped 3/8" rebar.

S 75° W 82.48' to nail and tag in N. side 12" Ash.

S 37° W 101.71' to nail and tag in E. side U.P.

G 13 Replace 3/4" pipe with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box.

N 19° E 61.19' (61.22' -R) to set nail and tag in W. side U.P.

S 58° E 49.73' to nail and tag in S. side U.P.

S 22° W 56.10' (-R & M) (56.15'-R) to NW corner block foundation of house.

S 7° E 54.90' (54.97' & 55' -R) to NE corner of block foundation of house.

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County East 71.56' to G 1-T14N-R3E. Date 08/04/94

HMMichael MacDonald P.S. County Representative

Burveyor's Michigan License No. $_{-}39088$

Date 11-10-94