Bay Co

Coms. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION

**ERKERTEXXXIAMETOR** 

Engineering and Architecture

## LAND CORNER RECORD

T. 15 N.R. 4E

			Bay	COUNTY
DESCRIPTION OF CORNERCO	mmon to	Sections 11, 12, 13, 14		
CORNER MONUMENT	2" x 18	" Iron Rod		
DATE MONUMENT PLACED AND WI				
WITHESSES TO CORNER		South 331 Fence Corner		
N N		North 25.6' Fence Corner		
		NNW 30.8 SE Cor. Concrete Pur	mp Ba <b>se</b>	
AMI	<b>D</b>			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

A 1/4" iron rod was located in the center of the road by using the old witnesses. This was replaced by a 1/2" iron and rod. No new witnesses established.

SURVEYOR'S SEAL

CC: Bay Co. Rd. Comm. SIGNED \_\_\_\_\_\_\_ DATE \_\_\_\_\_\_\_ A. V. McCann 13036