HENONLINE

MAY 2 0 1897

REMON. COR. C-11, GARFIELD TWP. LAND CORNER RECORDATION CERTIFICATE Filing Paguiroment of Act 74, Mich. P.A. 1970.

For corners in Bay	Filing Requirement of Act 74, Mich. P.A. 1970			: ,	003	284
(County)	Located in:	Corner Code #		_		
		0.44		æ_ <i>2</i>	닭	
Public Land Survey	T 16N R 3E	C-11		RE GI	23	
	T R		1	55. 1.5.(മ	刀
	ή "i'	· · · · · · · · · · · · · · · · · · ·			<u>.</u> =	RECORDED
2. Property Controlling	s T R			- P	w	B
In Section	S T R			<i>∯</i> ∺ੁੰ	3	ŒD
3. Miscellaneous	S T R			58 \$	-	
Property in Sec.	S TR		Register of Deeds	Stamp & File N	umber	
4. Lot No. , Recorded Plat				<u> </u>		
· · · · · · · · · · · · · · · · · · ·			ABC	D F F G	птл	KLN
5 Privato Claims			ABC	יוני ע	11 T U	7/ 17 1

1, <u>JERRY JONES</u>, in a field survey on <u>MAY 15</u>, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 1 4 5 6 8 16 7 8 วัด 28 27 10 29 11 12 13
- A. Description of original monument and accessories and/or subsequent restoration:
- C-11 Corner common to Sections 29, 30, 31 and 32

1831, R. Clark, set post, GLO notes
Co. Road Comm Records - no date, found 3/8" re-rod
1967, Edmands Engineering, breakdown for Sec 30, 31 and 32, found iron
C.P. Co. Maps, no date, Sec 29 and 32, found iron
1972 Edmands Engineering, rec. survey, L-673, P-269, no call, distance to D-

1972, Edmands Engineering, rec. survey, L-673, P-269, no call, distance to D-11 given
1977, Edmands Engineering, rec. survey, L-818, P-484, no call, distance to D-11 given

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- C-11 Corner common to Sections 29, 30, 31 and 32

Found rod in mon box per surveys by Bay Co. Road Comm. and Edmands Engineering

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-11 Corner common to Sections 29, 30, 31 and 32

Found rod in mon box per surveys by Bay Co. Road Comm., and Edmands Engineering; replaced rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838, and is the best available evidence of the position of the accepted corner.

N 10 Deg E, 132.50', nail and plastic disc in power pole S 45 Deg W, 43.50', nail and plastic disc in corner fence post S 50 Deg E, 87.24', NW cor house (not porch) concrete APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date /3 June 96

MJM
Michael MacDonald P.S.
County Representative

S 45 Deg E, 53.45', center line 6" pipe

Surveyor's Michigan License No. 19838

Date /0/17/

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971

Revised Jan., 1983