MAY 2 n 1997

REMON. COR. 1-11, GARFIELD TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

003
 ~ ~ ~

200

For corners in Bay	i mig rieda	Tomon of Plat 1 is investigation	
(County)	Located in:	Corner Code #	
1. Public Land Survey	T <u>16N R 3E</u> T R T R T R	<u> </u>	RECORDED RECORDED RECORDED RECORDED RECORDED RECORDED RECORDED RECORDED
2. Property Controlling S in Section S	т <u> </u>		DROE 5
3. Miscellaneous S Property In Sec. S	T R T R		Register of Deeds Stands & The Number
Lot No, Recorded Plat Private Claims			ABCDEFGHIJKLM
_			

I, <u>JERRY JONES</u>, in a field survey on <u>OCT 1</u>, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 3 4 5 18 16 б 7 22 8 9 วัก 23 9 10 28 26 30 29 11 12 13
- A. Description of original monument and accessories and/or subsequent restoration:
- 1-11 Corner common to Sections 26, 27, 34 and 35

1830's, GLO, set post

1909, C. Thornthwaite, found post

1973, L. McGinnis, LCRC, mon box

1973, L. McGinnis, rec survey, L-716, P-549, found fron

1974, L. McGinnis, rec survey, L-735, P-574, found mon box

1977, Edmands Engineering, rec survey, L-815, P-432, found mon box

1980, E. Goss, rec survey, L-897, P-315

1981, D. Ledy, rec survey, L-918, P-507

1982, R. L. Merry, rec survey, L-922, P-714

1984, R. L. Merry, rec survey, L-1039, P-881


1986, D. Burgin, rec survey, L-1035, P-542

1986, D. Burgin, rec survey, L-1035, P-536

1989, D. Ledy, rec survey, L-1137, P-994

1989, M. MacDonald, rec survey, L-1115, P-870

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date __/S Oct96
MITH______
Michael MacDonald P.S.



WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner common to Sections 26, 27, 34 and 35
 Found nail per surveys by C. Thornthwaite, L. McGinnis, E. Goss, D. Ledy, R. L. Merry, D. Burgin, M. MacDonald, Wade-Trim and LCRC by L. McGinnis
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 26, 27, 34 and 35
 Found nail per surveys by C. Thornthwaite, L. McGinnis, E. Goss, D. Ledy, R. L. Merry, D. Burgin, M. MacDonald, Wade-Trim and LCRC by L. McGinnis, replaced nail with 5/8* rod and brass cap stamped Bay County Remonumentation PS 19838 in mon box, and is accepted as the best available evidence of the position of the accepted corner.

N 50 Deg W, 57.53', nail and BC disc in power pole (1986 wit.)

S 75 Deg W, 96.95', nail in power pole

Surveyor's Michigan License No. 19838

S 45 Deg W, 55.06', NE cor building (store) (1974 wit.)

N 45 Deg E, 56.72', SW cor building (bar) (1980 wit.)

N 45 Deg E, 53.33', SW cor sidewalk

\$ 50 Deg E, 88.58', nail and BC disc in power pole

N 40 Deg W, 65.39, NE'ly cor square sign post

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971 Revised Jan., 1983