O GURVEY &	n 5
THENTALL	7
REMONUMENTATIO	

MAR 3 1 199A

Bay County Remonumentation

Fo	COMMISSION or comers in	LAND CORN Filing Requi	ER RECORDATION CERTI rement of Act 74, Mich. P.	to (<u>λ</u> ⊆Σ)
_	(County)	_ Located In:	Corner Code ##	
1.		T _17N_R _4E_ T _17N_R _4E_ T R	D-3 E-2	II 17 AH '93
2.	Property Controlling in Section	T R S T R S T R		LIBER 003 page 44
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. 5.	Lot No , Re-			A B C D E F G H I J K L

Craig W. McVean August 27 93 in a field survey on . . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

D-3 Set post - J. Burt, 1843. Maple 20" N 35° W 7 L. Birch 8" S 53° E 23 L.

L.C.R.C. - L. 2, P. 55 - 1974 - Porter. L.C.R.C. - L. 2, P. 476 - 1977 - Sedgeman. M.D.O.T. witness card. Recorded Surveys - L. 849, P. 985 - 1977; L. 1090, P. 431 -1988; L. 752, P. 336 - 1975.

E-2 Set post - J. Burt, 1843. Hemlock 8" S 59° E 9 L. Elm 15" N 31° W 9 L.

L.C.R.C. - L. 2, P. 279 - 1977 - McGinnis. Recorded Surveys - L. 762, P. 155 - 1975; L. 1042, P. 103 - 1987.

10

11

12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-3 Found 3/4" pinch pipe in mon. box per recorded L.C.R.C.'s. Distance W fits M.D.O.T. witness card. Distance E fits recorded surveys. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 10-21-93.

Found 3/8" iron rebar per L.C.R.C. - L. 2, P. 279 and recorded surveys. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 10-21-93.

OF MICHIG CRAIG W. McVEAN **PROFESSIONAL** SURVEYOR No. 39088

C. Description of monument for corner and accessories established to perpetuate locating the position of the connection.

D-3 Replaced 3/4" pinch pipe with 2-3/4" Bay County brass cap on 5/8" rebar in mon. box. N 45° W 47.47° to nail and tag in E side cutoff U.P. S 0° E 24.60' to nail and tag in W side RR tie anchor post. N 36° E 130.40' to SW corner of House #761. N 58° E 180.55' to SE corner of garage.

Replaced 3/8" rebar with 2-3/4" Bay County brass cap on 5/8" rebar in mon. box - 6" below gravel road. N 85°E 54.00' to nail and tag in S face 8" Elm. N 15° E 104.94' to nail and tag in E face telephone pedestal post.

N 15° W 126.03' to nail and tag in E face 8" Pine. N 50° W 59.93' to nail and tag in NE face 12" Pine. N 35° E 44.37' to centerline 4" pipe fence post.

Signed by Orang Will	Mallen Date 12	2/
	088	•