## SURVEY &

Surveyor's Michigan License No. \_

## **Bay County Remonumentation**

For	MAR 3 1 1994 Corners IDMMISSION	Filing Requirement of	RDATION CERTIFICATE Act 74, Mich. P.A. 1970	LIBER $003$ PAGE $4$
	Bay (County)		er Code <del></del>	RE ZZ  REGIST AY COUP
1.	Public Land Survey	T_17N_R_4E T_17N_R_4E TR		II 17 III
2.	Property Controlling 5 in Section 5	6 T R		<b>19</b>
3.	Miscellaneous S Property in Sec.	S T R	Reg	ister of Deeds Stamp & File Number
		orded Plat		A B C D E F G H I J K L
	•			2 6 5 4 9 3 1 2
	kaje #			
1, _	Craig W. McVean	a field survey on August 27	, 19 <b>93</b> ,	5
in i cur Mai abo Cor exp	ines 1 and 2 above were in co rent manual of survey instruction nagement or by a decree of a Co ove were in conformance with the out of Law; established, re-est pressed below: TE: Not more than 4 corne	ements of P.A. 74, Michigan P.A. of 1970, the informance with regulations and rules the ons of the United States Department of the urt of Law and/or that the corner points mere rules of the Michigan Board of Land Survisiablished, monumented, re-monumented ers, all in the same town and range, a	refore as required in the Interior, Bureau of Land Interior, Bureau of Land Intioned in lines 3, 4 and 5 eyors or by a Decree of a d, recovered, found as	6 18 17 16 15 14 7 8 19 20 21 22 23 9 10 30 29 28 27 26 11
	on this certificate.			12 31 32 33 34 35
A.	Description of original mor	nument and accessories and/or subse	quent restoration:	
	G-2 Set post - J. Burt, 1843. B. Oak 30" S 13° E 18 Lks.	e e	G-3 15" Hemlock at co W. Pine 15" N 10° W 29	
	Recorded Surveys - L. 812, 1992.	P. 241 - 1977; L. 1225, P. 393 -	County surveyor notes - Recorded Surveys - L. 9 L. 812, P. 241 - 1977.	- G. Turner, 1907. 100, P. 676, 1980; L. 1191, P. 665 - 1991;
			•	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				corner:
	G-2 Found 3/8" rebar per recorded surveys. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 10-21-93.		G-3 Found 3/4" outer diameter iron pipe per recorded surveys. Fits County surveyor notes W within 3.3' and E per record call. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 10-21-93.	
		CRAIG W.  McVEAN  PROFESSIONAL SURVEYOR  No.		
,		39088		•
C.				
•	G-2 Replaced 3/8" rebar with 2-3/4" Bay County brass cap on 5/8" rebar in mon. box.  N 54° E 35.91' to nail and tag in S face U.P.  N 66° E 20.95' to chiseled 'x' on top 18" concrete culvert.  N 58° W 46.27' to nail and tag in N face U.P.  S 44° W 50.29' to nail and tag on top 24" plastic culvert.		G-3 Replaced 3/4" pipe with 2-3/4" Bay County brass cap on 5/8" rebar in mon. box.  N 52° E 44.47' to nail and tag in W face telephone pedestal post.  N 33° W 57.05' to nail and tag in SW face U.P.  S 62° W 41.84' to nail and tag in SE face U.P.  S 50° E 64.23' to nail and tag in N. face guy pole.	
Sig	ned by Craig 1	V. Mellem	Date	7/93

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983