0	GURYEY &
L eve	MONTHEETHER

MAR 3 1 1994

For corners in Bay

Lot No.

Private Claims _

County

Public Land Survey

Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

LIBER	003	PAGE	31
5A	Z .	330	1
nus L		22	1728
**************************************			RECORDED
E	= 1	o)	S .
			₩
 	1 1 2 T		

_ , Recorded Plat _

Register of Deeds Stamp & File Number

Located In:

T T17NR R4E

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A B C D E F G H J K L M

2
3
4
7
8
19
20
21
22
23
24
9
10
30
29
28
27
26
25
11
12
31
32
33
34
35
36

A. Description of original monument and accessories and/or subsequent restoration:

<u>I-1</u> intersect N boundary 12 Lks. E of post - set post - J. Burt, 1843.

W. Pine 6" \$ 7-1/2° W 30 Lks. Tamarack 4" \$ 6-1/2° E 29 Lks.

L.C.R.C. - L. 2, P. 85 - 1974 - McGinnis. Recorded Surveys - L. 713, P. 608 - 1973; L. 894, P. 546,

Records. Set PK nail 7.92' E of I-13, T18N, R4E.

Bay County Records.

Recorded Surveys - L. 1, P. 102 - 1973, Arenac County

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-1 Closing corner common to Sec. 2 and 3, T17N, R4E. PK nail not found. Set 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box at recorded GLO closing E of I-13, T18N, R4E and recorded surveys. Monument is accepted as a careful and faithful re-establishment of the position of the original corner. Accepted by Bay County Peer Review Group on 10-21-93.

J-1 1/4 corner common to Sec. 2, T17N, R4E. Found 3/8" x 24" rebar inside 2" x 6" pipe per L.C.R.C. and recorded surveys 0.23' N of standard line at occupation line to S and at proportional distance E and W. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner. Accepted by Bay County Peer Review Group on 11-4-93.

Recorded Survey - L. 713, P. 608 - 1973; L. 894, P. 546 - 1980.

J-1 Not set in original survey.

L.C.R.C. - L. 2, P. 85 - 1974 - McGinnis.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-1 Set 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon.

S 70° W 144.10' to nail and tag in N side U.P.

N 30° W 230.78' to nail and tag in E side U.P.

S 75° E 123.19' to nail and tag in W side U.P.

S 25° E 113.31' to nail and tag in W side 14" tree.

W 7.92' to 3" Arenac County brass cap in mon. box. (I-13 - T18N - R4E)

J-1 Replaced rebar and pipe with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box. Set on standard line.

S 3° E 32.72' to nail and tag in W side 8" Cedar.

S 30° E 40.20' to nail and tag in SW corner RR tie post.

S 38° W 147.29' to NW corner block foundation House #3759.

S 63° E 78.87' to nail and tag in S side 15" Maple.

W 6.69' to 3" Arenac County brass cap in mon. box. (J-13 - T18N - R4E),

Signed by Oracle M. Ma Olem— Surveyor's Michigan License No. 39088

12/20/93

CRAIG W. McVEAN PROFESSIONAL SURVEYOR

No.

FORM APPROVED BY MICHIDAY STATE BOARD OF SURV

OFESSIONAL BUSSED JAN., 191

28, 1971