(200	SURVEY &
FEW	ONUMERO

MAR 3 1 1994

(County)

Bay County Remonumentation

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MARKE	anai	SSICN
---------------------------------------	-------	------	-------

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

LIBER	00	3 page	32
BAY COUNTY MICHOAN	1,7,2,5,1,7,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1	Dec 22 11 16 AM '93	NECONDED

Public Land Survey

For corners in Bay

> T_17N_R_4E_ T 17N R 4E

Located In:

Register of Deeds Stamp & File Number

Property Controlling in Section

Miscellaneous Property in Sec.

4. Lot No.

_ . Recorded Plat

Craig W. McVean

5 Private Claims

August 26 in a field survey on

93

19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12 13 L-3 W. Pine 30" for Sec. corner - J. Burt, 1843.

Recorded Surveys - L. 737, P. 290 - 1974; L. 1115, P. 905 - 1989.

10

11

Description of original monument and accessories and/or subsequent restoration:

K-3 Set post - J. Burt, 1843. Hemlock 8" S 31° E 21 Lks. Hemlock 11" N 10° W 20 Lks. L.C.R.C. - L. 2, P. 225-1977 - Sedgeman Recorded Surveys - L. 737, P. 290 - 1974; L. 1121, P. 821 - 1988; L. 1113. P. 54 - 1989.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-3 Found 3/8" rebar over 3/4" pipe per L.C.R.C. - L. 2, P. 225 at N-S occupation line. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 11-4-93.

L-3 Found 1" iron pipe per recorded surveys at N-S occupation line. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 11-4-93. OF MICHIGAN

POFESSION C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

K-3 Replaced 3/8" rebar and pipe with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box. N 25° E 83.90' to nail and tag in W side 30" Maple. N 43° E 31.38' to nail and tag in SE side 24" Maple. N 58° W 56.97' to nail and tag in S side U.P. S 73° W 85.98' to nail and tag in SE side 12" Pine. S 39° E 123.07' to NW corner block foundation house.

Replaced 1" pipe with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in mon. box. S 6° W 22.79' to nall and tag in E side U.P. N 27° W 141.69' to SE corner foundation House #2755. N 53° W 196.65' to SE corner foundation House. S 44° E 152.21' to SW corner foundation liouse #2762. N 36° E 187.47' to NW corner garage foundation House #2763.

Surveyor's Michigan License No. _

Date /2/20/93

CRAIG W. **McVEAN** ROFESSIONAL SURVEYOR No. 39088