SUHVEY &	Bay Cou	unty Remonumentation	1			
REMONUMENTAT  MAR 3 1 1994  For corners in	LAND CORNER	R RECORDATION CERTIF ment of Act 74, Mich. P.A	•	LIBER OC	13 page	30
Bay COMMISSION	Located In:	Corner Code ##		S 2. 12.	)EC	
Public Land Survey	T _17N_R _5E_ T _17N_R _5E_ T R T R	A-1		### \$2/47 VI 1.00 XLX DO. 1 1.00 XLX DO. 1	22 11 16	RECORDE
in Section S	TR			80337 80337		Ö
	T R		Register of	Deeds Stam	p & Ffle N	umber
4. Lot No, Recorded 5. Private Claims, in a fit do hereby certify that under requirement in lines 1 and 2 above were in conformance manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rull Court of Law; established, re-estables.	eld survey on August its of P.A. 74, Michigan P.A. o mance with regulations and of the United States Depart fLaw and/or that the corner les of the Michigan Board of	31 93 If 1970, the corner points mention of the Interior, Bureau of Land Surveyors or by a Decree	the	3 C D E F	G H	J K L M
expressed below:  NOTE: Not more than 4 corners, on this certificate.	all in the same town and	d range, may be recorded	103 11 123	29 -20	3-1-34	-3536-
A. Description of original monume  A-1 Set post common to 4 town Beech 14" S 7° W 16 Lks. Pine 11" N 19° W 28 Lks.  L.C.R.C L. 1, P. 47 - Aren McGinnis. Recorded Surveys - Arenac County Records - 1973; Records - 1981.	ships - J. Wampler, 1822. ac County Records - 19 L. 1, P. 100 - 1	B-1 Set post Ash 7" N 40° V Ash 9" S 6° E 9  Recorded plat County Record L. 2 of Plats, P	- J. Wampler, 182 V 8 Lks.	Sub." L. 5 of it of "Al Heppr		
R Description of corner evidence	found and/or method a	nolied in restoring or reesta	iblishina comer			•

- scription of corner evidence found and/or method applied in r
  - Township corner common to T17N, R4&5E, and T18N, R4&5E. Found 3/8" rebar per L.C.R.C. - L. 1, P. 47, Arenac County Records. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 11-4-93.
- B-1 Standard 1/4 corner common to Sec. 31, T18N, R5E, and Sec. 6, T17N, R5E. Found 3/4\* pipe. Pipe fit recorded plat distances to E. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 11-4-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1 Replaced 3/8" rebar with Bay-Arenac County 3-1/4" brass cap

on 5/8" rebar in mon. box. N 30° E 34.59' to pk nail and tag in NE corner of E wing wall.

N 86° E 45.26' to capped 3/8" rebar.

\$ 42° E 55.86' to pk nall and tag in NE side U.P.

\$ 58° W 26.81' to capped 3/8" rebar.

Replaced 3/4" pipe with Bay-Arenac County 3-1/4" brass cap on 5/8" rebar in mon. box. N 25° E 51.96' to nail and tag in W side U.P.

N 25° E 51.50° to mail and tag in W side U.P.

S 45° E 59.91' to nail and tag in N side 10" Cottonwood.

S 10° W 31.63' to nail and tag in E side U.P.

E OF MICHIGAN CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088 Surveyor's Michigan License No. OFESSION PU