SECTION

## LAND CORNER RECORDATION CERTIFICATE PAGE 295 Filing Requirement of Act 74, Mich., PA 1970

For Corners In: BENZIE	Located In Co	mer Code #	STATE OF MICHIGAN RENZIE COUNTY
(County)			RECORDED
1. Public Land Survey	T 25N R 14W	E-13	1 FEB 2000 1:50:59 PM
2. Property Controlling	s T R		NICHELLE R. GRAY REGISTER OF DEEDS
in Section	s - r - R	<u></u>	# PAGES ONE
3. Miscellaneous			
Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		ABCDEFGHIJKLM
5. Private Claims:			'
J. 1 (17415 Claims.			3
Lighn B. Smendzuik in a field survey on September 15, 1999 do hereby state that			
			5
required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or			6 18 17 16 16 16 13
that the corner points ment	tioned in lines 3, 4 and 5 above were in co loard of Land Surveyors or by a Decree of	onformance with	7
established, re-established,	, monumented, recovered, found as expres	sed below:	8 19 20 21 22 23 24
NOTE: Not more than	2 corners, all in the same town and	range, may	10 30 28 27 26 25
be recorded on this certificate.			
			12 31 32 33 34 35 36
			13
A. Description of origina	I monument and accessories and/or su	ubsequent restoration:	
			E 34 links. 1900: J.H. Millard, says 12" Sugar,
squared, notched and marked stands at the crossing of old blazes. He witnessed it with 11" Lynn N87°E 20.46' and 18" Sugar S25 ½°E 34.98'. 1911: Frank Haswell, Survey Record II, Page 114, shows break of all of Section 32 with numbers. Also shows he found old sugar corner tree and drove a 1" iron pipe in roots on North side. He also found old witness tree to Northwest. 1964: BCRC records show they found a 1½" iron pipe and witnessed it. 1969: Bill Batzer found a 1" iron pipe at 'T' intersection with witnesses. 1990: Richard Wilcox, Certificate of Survey in Liber 2, Page 116, found 1" iron pipe at comer and witnessed it. 1990: Richard Wilcox, LCRC recorded in Liber 1, Page 264, shows found 1" iron pipe.			
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:			
1999: Found a 1"x 18" iron pipe next to a ¾" x 12" iron rod. After pulling out all of these, there was still a beep in the bottom of the hole. The corner is in an area of fill of about 5'. Iron fit Wilcox witnesses and Haswell numbers. Believe the Haswell iron pipe was still in the bottom of the hole. The Benzie County Peer Group accepted the 1" iron pipe as the best available evidence of the perpetuation of the original GLO comer.			
		!	Ratified by Peer Group
In accordance with P.A. 345			In accordance with P.A. 345
		ı	Chairman
			Date <u> </u>
C. Description of monur	ment for corner and accessories estab	lished to perpetuate lo	ocating the position of the corner:
Set a standard 3" diame	eter Benzie County Remonumentation	Program concrete mor	nument with a brass cap in a monument box.
30" Beech N58°E	68.20' to a found 60D spike.		THE OF MICHIGAN
7" Ash S38°E 59.63' to a found double headed nail and washer.  Stop Sign Post S30°E 37.93'.  JOHN B.			
10° Cherry N27°W 41.32' to a found 60D spike.			
10° Cherry N27°W 41.32' to a found 60D spike.  Corner is in the intersection of North Manistee County Line Road and Willis Road to the South.  SMENDZUIK  LAND  SURVEYOR  No. 30895			
	•		THE STATE OF THE S
Signed by:	010	Date:	LAND SUMMER
Surveyor's Michigan	License No.: 30995		1,311000
our rejor a morngan		·····	