ngian na salah kacamatan na kacamatan kacamatan na kacamatan na kacamatan kacamatan kacamatan kacamatan kacama	
n de la companya de La companya de la co	LIBER 2 PAGE 210
WELDON TOWNSHIP For corners in LAND CORNER RECORDATION CERTIFIED Requirement of Act 74, Mich. P.A.	1970 BENZIE COUNTY
BENZIE COUNTY Located In: Corner Code #	, RECORDED
1. Public Land Survey T 25NR 14W G-8 T R T R T R T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R	22 JAN 1999 3:02:23 PM MICHELLE R. GRAY REGISTER OF DEEDS # PAGES
Property in Sec. S R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	, <u>АВС</u> D Е F G H I J K т.
	2 6 5 4 3 2 1
John B. Smendzuik, in a field survey on 12/3, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	5 18 17 16 15 14 13
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11
A. Description of original monument and accessories and/or subsequent restoration:	13
G-8: 1838: GLO set post - Sugar 14" N77°W 14 links and Sugar 10" S65°E 13 links. 196 no evidence how.	67: BCRC notes show corner established and
	Ratified by Peer Group
	In accordance with P.A. 345
B Description of corner evidence found and/or method applied in most in the	D-1 1/24/00
B. Description of corner evidence found and/or method applied in restoring or reestablishing cor	rner:
G-8: 1998: Found 3/4" x 12" iron pipe, 6" below existing grade and on old occupation to West. Iron is 36' South of fence line to East. Iron is on line between corners at G-7 and G-9 and is within 0.87' of a split of the distance between those corners. The Benzie County Peer Group accepted the 3/4" iron pipe as best evidence of an locally accepted corner.	
C. Description of monument for corner and accessories established to perpetuate locating the po	sition of the corner:
G-8: Removed the 3/4" iron pipe and set a 3" diameter Benzie County Remonumentation P in a monument box.	Program concrete monument with a brass cap
5" Red Pine N33°E 90.44' to found 60D spike in tree with blaze. 12" Red Pine N42°W 71.26' to found 60D spike in tree with blaze. Power Pole S79°E 32.53' to found 60D spike. 16" Maple N33°E 123.73' to found 60D spike. Monument box is in the centerline of Pioneer Road.	
Signed by AA S D 11	1/22/99
Signed by Date Date	1166 177