LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Benzie	Located in Co	orner Code #		
(County)				
1. Public Land Survey	T <u>25N</u> R <u>14W</u> T R	<u>C1</u>		
Property Controlling in Section	S T R			
Miscellaneous Property in Section	S T R S T R			
r reporty in decision	S T R		Register of Deeds Stamp	& File Number
4. Lot No:	Recorded Plat:		A B C D E F G H !	J K L M
5. Private Claims:			2 6 5 4 3	-2-1-1-
I, <u>Craig W. McVean</u> , in a field survey on <u>July 7</u> , 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			4	
NOTE: Not more than a be recorded on this cer	2 corners, all in the same town and rtificate.	range, may	10 30 29 28 27 11 12 31 32 33 34 13	
A. Description of original monument and accessories and/or subsequent restoration:				
C1 – 1838 – GLO – Austin & Alvin Burt – Intersected North boundary 12 L. East of Comer 1) Sugar 10" S25°E 21 L. 2) Sugar 18" S52°W 36 L 1900 – CSR – L. 1, p. 6 – C. P. Tuller Survey of Sec. 5. The NW Corner was all living and post had been set in the position 1979 – L. 1, p. 52 – C. F. Roser - Re-established closing corner to Secs. 5 & 6 on South line of Sec. 32 (26-14) and on line across fd. ¼ Corner to South and fd. 2" pipe, 0.98' South. Fits C. P. Tuller Survey, Sec. 5 – May 1900. Set DNR Mon. (buried) in approx. center of E-W Dirt. Co. Rd. 3) 24" Maple S18°E 45.59'; 4) 16" Maple S35°W 39.90'; 5) 15" Cherry Tw. N51°W 58.44'; 6) Set Ced. Post with loc. tag due S. 33'; 7) Fd. 2" pipe (buried) S00°45'E 0.98' 8) Cor. To Secs. 31 & 32 (26-14) N89°38'W 276.70'				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
C1 – Closing corner common to Sections 5 & 6, T25N, R14W - Found 4" aluminum DNR cap on 1" iron pipe, and Roser witnesses #3, 4, & 5 fitting position. GLO witnesses are gone. We calculated the DNR Mon. to be 0.07' South of standard line. Replaced DNR Mon. with Benzie Co. Remon Monument on Standard Line – 0.07' North. Centerline of E-W gravel road is 2' N. Also found 2" iron pipe is 1.09' South for the Amended Monument to 'C1'. This 2" iron pipe is believed to be Tuller's perpetuation of the original closing corner. Benzie Co. Monument accepted as the best available evidence of the position of the closing corner on the standard line.				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
C1 – Benzie County Remonumentation Monument being a stamped 3" Brass Cap on a ¾" x 36" iron pipe encased in 4" x 36"				
S21°E 46.03' to set South 1.09' to fd. 2' S33°W 39.99' to se N53°W 58.18' to se Set Blue Carsonite	t N & T in NW side 8" Cherry t N & T in W. side 27" Sugar Maple (# " iron pipe (#7) – Amended monumen et N & T in SE side 21" Sugar Maple (# et N & T in NE side 18" Twin Cherry (# Post with loc. tag 33' South	nt (AM) #4) #5)	25D) 4- (040) T00N D44N - 5	
N87 35720 VV 276.5	59' (276.57' – Grid) (7.92' – GLO, 279	0.64° – GPT, 276.70′ – 0	טרא) זס יטונזי, 126N, R14W – E 	senzie Co. Mon. (#8)
Signed by: O	ing W. Miller	Date:	///C/// 19 19 17 1	OF MICHIGAN
Surveyor's Michigan	License No.: 39088		PRO	OFESSIONAL DESCRIPTION OF SURVEYOR NO. 39088
FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSION SURVEYOR 144 28, 1971 ESSION SURVEYOR 14 1975 Revised Jan. 1983				
				Revised Oct. 1995