LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Benzie	Located In	Corner Code #	
(County)			
1. Public Land Survey	T 25N R 14W	<u>C2</u>	
2. Property Controlling in Section	T R		
3. Miscellaneous Property in Section	6 T R 6 T R 6 T R		Register of Deeds Stamp & File Number
4. Lot No: F	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims:			2 6 5 4 3 2 1
requirements of PA 74, Michigand 2 above were in conformathe current manual of survey Interior, Bureau of Land Mana corner points mentioned in line of the Michigan Board of Lestablished, re-established, m	d survey on July 8, 2009 do her gan PA of 1970, the corner points ance with regulations and rules they instructions of the United State gement or by a decree of a Court ces 3, 4 and 5 above were in conformand Surveyors or by a Decree onumented, recovered, found as excorners, all in the same town	mentioned in lines 1 erefore as required in s Department of the of Law and/or that the rmance with the rules of a Court of Law; xpressed below:	3 4 7 8 9 10 11 12 12 15 16 15 14 13 17 16 15 17 17 18 19 19 10 19 19 10
be recorded on this certif			11 31 32 33 34 35 36
			13
A. Description of original monument and accessories and/or subsequent restoration:			
C2 – 1838 – GLO – Alvin & Austin Burt – Set ¼ Post 1) Hemlock 36" S25°W 43 L. 2) Sugar 26" N38½°E 30 L 1900 – CSR – L. 1, p. 6 - C. P. Tuller. Fd. ¼ post by the field notes and wit. trees. The sugar was fallen down and rotten and only the stump of the Hemlock was left 1979 – LCRC – L. 1, p. 52 & DNR Project #76-20, C. F. Roser - Fd. ¾" pipe with 3 large stones around it for W ¼ corner Sec. 5, which fits C. P. Tuller Survey of Sec. 5, dated May 1900. Fd. ¾" Pipe replaced with DNR monument and cedar post. 3) 11" Tw. Maple S75°W 15.6'; 4) 9" Maple N23°W 33.4'; 5) 5" Maple N19°E 26.1'. N-S Random due West 11.67'.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
C2 – ¼ corner common to Sections 5 & 6 - Found 4" DNR Aluminum cup mon. on 1" x 36" iron pipe with older 1" O.D. x 36" alongside with 1 large & 2 medium size stones around monument. Found all of C. F. Roser witnesses. GLO witnesses are gone. Cedar post is rotten. Accepted DNR monument as a careful and faithful perpetuation of the position of the original corner.			
·		• •	locating the position of the corner:
encased in 4" x 36" c N22°E 26.38' to set r N23°W 33.89' to set S76°W 16.45' to set	concrete cylinder. Placed 1 larg nail & tag in West side 11" Red nail & tag in West side 13" Sug nail & tag in South side 10" & 1 ail & tag in North side 8" Red M	je and 2 medium sized sto Maple in a clump of 6 (#5 ar Maple (#4) 5" twin sugar maple (#3)	CRAIG W. MCVEAN PROFESSIONAL CRAIG W.
Signed by: One	www. Mada	Date:	No. 39088