## SURVEY & REMONUMENTATION

MAY 0 5 1997

\_\_\_ , Recorded Plat .

LAND CORNER RECORDATION CERTIFICATE

LIBER 🚄	PAGE	JO
---------	------	----

LIBER	<u>.</u>	PAGE
CATE		

				e a	8. 19	k & Ye	2 W E	214	14
Of	corners	in	CO	/}	W.		<u>ن</u> ا	√.)	ý

Private Claims \_\_

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN BENZIE COUNTY RECORDED

	Benzie	Located In:	Corner Code ##	
	(County)			
1.	Public Land Survey	14W T 26N R <b>1</b> €₩	₩-7	
		T R		
		T R		
		T R		
2.	Property Controlling	S T R	<del></del>	
	in Section	S T R		
3.	Miscellaneous	S T R	-	
	Property in Sec.	S T R		

1/22/1997 1:56:10 PM MICHELLE R. GRAY REGISTER OF DEEDS # PAGES \_\_\_\_\_

Register of Deeds Stamp & File Number

			,			
John	в.	Smendzuik	, in a field survey on .	4/11 and	6/26	
do heret	y ce	rtify that under red	quirements of P.A. 74, Mid a conformance with regi	chigan P.A. of 1970	i, the corner	pointsmentioned
			uctions of the United Sta			

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ■bove were in conformaπce with the rules of the Michigaπ Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: A-7: G.L.O. set post and witnesses - 10" Sugar N16°W 5.94', 11" Sugar S76°W 21.78', 8" Sugar N32°E 13.86' and 13" Sugar S55°E 13.20'. Record of Surveys, Page 89, shows work being done in Section 18 in July of 1868. Surveyor's Record II, Page 58, Frank Haswell notes found old post. G.A. Shadko, Michigan Department of Conservation, in June of 1944, found an iron pin and set a D.N.R. concrete monument. Harold Bruning in 1972 and Carl F. Roser in 1988 filed Act 74 records with corner being D.N.R. monument in Liber 1, page 129 and Liber 1, page 248.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**4-7:** Found D.N.R. concrete monument next to a 1/2" iron pipe inside a 3/4" iron pipe 30" long.

> Ratified by Peer Group In accordance with P.A. Chairman (194)

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-7: Removed D.N.R. and iron pipe remains, after Road Commission work to rebuild County Road 669, and set a 3" diameter Benzie County Remonumentation Program concrete monument in a monument box.

24" Maple N68°E 69.531 S73°E 18" Maple 89.25 S30°E 72.51' Power pole

5/8" x 24" rebar N47°E 65.45"

5/8" x 24" rebar S47°W 64.05'

igned by		Date _	1/21/97
unever's Michigan License No	30895	X	FORM ADDROUGH BY MIPMICAN STATE BRAND OF LAND SURVEYORS. JAM. 28, 15