

MARC 1 S 1999

SECTION

Surveyor's Michigan License No._

24600

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 2 PAGE 180

For corners in Almira Township	LIBER & PAGE 10V
BENZIE Located In: Corner Code #	STATE OF MICHIGAN BENZIE COUNTY
1. Public Land Survey	RECORDED 7 JAN 1999 4:05:17 PM MICHELLE R. GRAY
in Section	REGISTER OF DEEDS # PAGES Register of Deeds Stamp & File Number
4. Lot No Recorded Plat 5. Private Claims	
i, JOHN F. KORR, JR, in a field survey on December 11, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established re-established, monumented, re-monumented, recovered, found as expressed below:	A B C D E F G H I J K L 2 - 6 - 5 - 4 - 3 - 2 - 1-
NOTE: Not more that 4 comers, all in the same town and range, may be recorded on this certificate.	5 18 17 16 15 14 13
A: Description of original monument and accessories and/or subsequent restoration:	8 19 20 21 22 23 24
July 1850 GLO - Survey - Set post for corner with two Witnesses: S44°W - 46.98' - W. Pine 14"; N40°E - 13.86' or 15.18' - Aspen 10".	11
July 1975 - Wm. B. Batzer (survey L. 1, P. 415) and (LCRC L. 1, P. 118) J#7593, found a 3/8" rod for work in Section 20; 3 Witnesses; S28°E - 13,52' - Cherry 10"; S82°W - 42,75' - Maple 1 N6°W - 60,41' - W. Pine 24".	iron 12 31 32 33 34 35 36 0"; 13
June 1976 - Wm. B. Batzer J #7593, found 3/8" iron rod, same witnesses as in LCRC from 1975	5;
1977 - Carl Roser (DNR) during a temporary survey found ½ * iron 3' North of E-W road centerlin completed.	
June 1978 - Wm. B. Batzer (survey L. 1, P. 611) J # 7851, found 3/8" iron rod, same witnesses a - 60.43' - W. Pine 24"; S25°E - 13.53' - Cherry 18"; also Found new iron rod N6°30'00"W - 9.42	?.
December 1979 - Corey Hughes, found both the Batzer corner as per LCRC 1975 and Carl Rose 22 J. #79547.	
April 1988 - Max Harris J. #88-4-1988, certificate of survey tied to corner No. I.D. stated, for world applied in restaring or recently	
B. Description of corner evidence found and/or method applied in restoring or reestable December 1998 - I found the ½' iron rod as recorded by Wm. B. Batzer 2.5 feet East of a fence I centerline of Fogg Road. This corner is also 2 feet West of the centerline of Hulbert Road running the corner called for by Carl Roser was not present and no other evidence was found. I found 1 witnesses: 14" Oak - S84°W - 42.73'; 20" W. Pine - N18°W - 54.97'; p.p S45°E - 72.34'. locally used and accepted corner.	ine running to the North & 11.5 feet south of the E-W ng South. The other corner as called for by Batzer in 1978 witness by Batzer: 26" W. Pine - N06"W - 60.43" and als
C. Description of monument for corner and accessories established to perpetuate loc	ating the position of the corner:
At the position of E-9, I set a Standard Benzie Co. Remonumentation Monument, witnessed by 26" W. Pine - N06°W - 60.43' 14" Oak - S84°W - 42.73'	the following:
20" W. Pine - N18°W - 54.97' p.p S45°E - 72.34'	atified by Peer Group accordance with P.A 345 lairman 1924 198
Signed by John F. Kory, Jr. Date	· <u>12/29/98</u>