Remonumentation corner under P.A. 345, Michigan P.A. of 1990 LAND CORNER RECORDATION CERTIFICATE ALMIRA TWP. Filing Requirement of Act 74, Mich. P.A. 1970 | IRFR 2 PAGE 175 For corners in BENZIE Corner Code # Located In: (County) STATE OF MICHIGAN T27NR 13W F5 1. Public Land Survey BENZIE COUNTY RECORDED 19 Jan 1998 2:52:00 PM 2. Property Controlling MICHELLE R. GRAY REGISTER OF DEEDS in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number \_ , Recorded Plat 4. Lot No. 5. Private Claims 1 2 3 1, Matthew T. Mokanyk , in a field survey on December 29 , 19 97 do hereby certify that under 4 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 6 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 8 GC# 97480.01 q NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 10 11 12 A. Description of original monument and accessories and/or subsequent restoration: August 19, 1850-GLO Surveyor- Set Ironwood post May 11, 1978- Unrecorded L.C.R.C. from Benzie June 12, 1992- L.C.R.C. Liber 1, page 268, filed by County Road Commission-Found I" Pipe. and noted two accessories: R. Max Harris. Found 1" iron pipe. Four N49W 14lk. 6" Sugar (gone) Two accessories shown: accessories shown: 5" Maple N24E 36.63' S9E 22lk. 20" Sugar (gone) P. Pole S7W 33.40' 8" Maple N52E 63.61' 7" Maple N51E 67.50' February 24, 1879- Benzie County Surveyors Pole N14E 27 58' Records 1, Page 119 (D.F. Holden)- Established September 23, 1978- Harold R. Bruning Survey Job Twin 16" Basswood S82W 107.6' corner from original bearings. No. 78-2137- Found I 1/4" iron pipe. Four accessories shown: Elm 8" South 23.90' August 18, 1972- L.C.R.C. Liber 1, Page 113, filed by Larry M. Gerschbacher. Found I" iron pipe. Maple 9" N55E 63.63' Three accessories shown: Basswood 7" N09W 11.20' Spike in 10" Elm with R.L.S. cap #2728 N35W Maple 6" N26E 36.58' Ratified by Peer Group 11.65' (gone) In accordance with P.A. spike in 8" Elm S60E 49.21" (probably meant feet not inches) (gone) Chairman Spike in 6" Elm with R.L.S. cap #2728 South 23.90" 12/18/97 Date\_ (gone) SURVEY & REMONUMENTATION B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: December 1997- Gosling Czubak APR 0 7 1998 Remonumentation-Found 1/2" iron rod & cap #31611 inside 2" x 2 3/4' well point. Benzie County Peer Group accepted position of 2" well point for SECTION corner F5. Removed rod and well point. Set standard Benzie County Remonumentation Monument. OF MICHIGANIA C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; December 1997- Gosling Czubak Remonumentation \* PROH SUR!
NO 4206:
ARD OF LANDS!
VAY 14,19\* S MATTHEW 1 F5 (South 1/4 corner Section 9, T27N-R13W, Almira Twp.) Set standard Benzie County Remonumentation Monument: South ±5' to C.L. seasonal road S7W 33.35' to P.K. nail in E face guy pole S82W 107.6' to Dbl. Head nail/washer in N face twin 16" Basswood **PROFESSIONAL** N14E 27.58' to P.K. nail/washer in E face P. Pole SURVEYOR N51E 67.50' to Dbl. Head nail in SE face 7" Maple Signed by Watchew Highory Date\_

Surveyor's Michigan License No.