

APR 0 7 1998emonumentation corner under P.A. 345, Michigan P.A. of 1990 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

(County) 1. Public Land Survey 2. Property Controlling S in Section S	Filing Requirements of the control o	Corner Code #	LIBER 2 PAGE 1 STATE BEN 19 Jan 1 HICHE REGII # PA	OF MICHIGAN ZIE COUNTY ECORDED 1998 2:47:49 ELLE R. GRAY ETER OF DEEDS GES ON	PN
3. Miscellaneous S Property in Sec. S 4. Lot No, Recorded Pla 5. Private Claims	t		Register of De	·	I J K L
Matthew T. Mokanyk, in a fick requirements of P.A. 74, Michigan P.A. of conformance with regulations and rules the United States Department of the Interior, B that the corner points mentioned in lines 3 Board of Land Surveyors or by a Decremenumented, recovered, found as expression. NOTE: Not more than 4 corners, a on this certificate.	prefore as required in the fureau of Land Managem 3, 4 and 5 above were ince of a Court of Law; essed below:	current manual of survey instructions of the conformance with the rules of the Michigas established, re-established, monument (490.01)	ter 4 7 8 - 17 17 18 17 18 17 18 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18	21 22 28 27 33 34	-11 12 13 23 24 25 35 36
A. Description of original monumen August 1850 - GLO Surveyor - 15" Beer Corner with one accessory: N80°W - 15.8' - Beech 6" County Survey Records - Bk2, P.20 - Ja Ceder Post previously established for co Pettitt's record also shows several distant to property lines as well as ½ mile distant West, North and East.	umes Pettitt mer noes North	Ra In Ch	atified by Peer G accordance with airman 12 29 97	roup P.A. 345	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

December, 1997 - Gosling Czubak Remonumentation-Found bottom of cedar post 2' below surface and on N-S fence line. The post fits Pettitt's 1/2 mile distance North within 0.51'. Also, Pettitt calls for an E-W property line at 825' North of this corner. We measured ±822' North to an ancient, fallen fence line. Pettitt shows the corner being mid-way between the SW and SE corners of the section. The corner measures within 2' of being mid-way between the SW and SE corners of the section. While digging for the cedar post, two large rocks along with brown bottle glass were found. The Benzie County Peer Group voted to accept this corner if it could be recovered. Therefore, The Benzie County Peer Group accepted the position of this cedar post bottom for corner J7. Removed cedar post bottom and set Standard Benzie County Remonumentation Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J7 (South 1/4 corner Section 14, T27N-R13W)

Set standard Benzie County Remonumentation Monument:

North 14.65' to I 1/4" iron pipe

N50E 38.13' to Dbl. Head nail in NW face 12" R. Pine

S65E 60.16' to spike in S face 16" Maple

S40E 31.53' to spike in NE face 16" Maple

S10W 46.86 to spike in E face P. Pole

T. Makangh Date 12-30-97 Signed by Lathau Surveyor's Michigan License No.

S MICHIGANINA OF MICHIGAN Ph SU. 4206
4206
AND SURVEY
1975 **PROFESSIONAL** SURVEYOR