MALTIEU BY THE BERRIEN COUNTY COR<mark>111</mark>#9560 03/08/96 SURVEY PEER GROUP AS THE 03/08/96 OFFICIAL CORNER, UNDER MICHIGAN STATE REMON FEE \$2 345 OF 1990 MBLIG ACT BERRIEN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 corners in  $_{\odot}$ Located In: Corner Code ## £ 03 T \_4 SR 18 W 1. Public Land Survèy T4S. R19W. M-4 R R **Property Controlling** S Т R R S in Section R Miscellaneous S Т Register of Deeds Stamp & File Number R Property in Sec. .......... , Recorded Plat 5. Private Claims \_ , in a field survey on \_ MARCH 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 8 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 13 Description of original monument and accessories and/or subsequent restoration: (SEE BACK) SURVEY & REMONUMENTATION DEC 1 6 1996 COMMISSION B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 36" LONG, 1" IRON ROD WITH FLATTENED TOP. DISTANCES TO ADJACENT CORNERS WERE REASONABLE AND CONSISTENT (FROM RECENT SURVEYS). THE PERPETUATION OF THE CORNER AS EVIDENCED BY THE HISTORY OF WITNESS TIES APPEARS RELIABLE AND ACCURATE. Description of monument for corner and accessories established to perpetuate locating the position of the corner: REMOVED IRON ROD AND SET STANDARD 36" LONG, 1" IRON PIPE WITH BRASS PLATE WITH NEW MONUMENT BOX. CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THIS ORIGINAL CORNER. SET NAIL WITH BRASS TAG IN P. POLE S 22° E, 92.46'.

CENTERLINE TOP NUT OF FIRE HYDRANT S 40° E, 47.30'.

SET NAIL W/BRASS TAG IN 10" POPLAR S 85° W, 101.62'.

CENTERLINE CATCH BASIN RIM N 15° E, 53.84'. JOHN G. JOHN G Signed by Surveyor's Michigan License No 27449 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

3PAGE 340

LIBER

REVISED MAY 14, 1975 REVISED JAN., 1983 W ¼ Corner 7-4-18 Benton Township A-4 February 29, 1996

John Mullett D.S.

Set Post for Survey of Sec. 12-4-19 W. Wood 12" - S 62° W - 22 Links W. Oak 14" - N 47° W - 50 Links

1900± Will Cleary

Stone 2646' North of SW Corner

1920 & John Howard

1924 Stone

Locust - NE 47' Pine - SE 33'

Guy Pole - NW - 21.5' Guy Pole - SW - 26'

1948- B.C.R.C.

1960 Stone Locust NE 47'

Pine SE 33'

Guy Pole - NW 21.5' Guy Pole - SW 26' Iron S 33' & 113' Iron SW 46.55' Locust NE 46.5' 24" Pine E 31.7' 24" Pine SE 42.2'

1984 Kamer W&A

1" Iron Rod

Fire Hydrant S 80° W 46.90'

Centerline S Bound Lane N 45° W 33.35' Centerline N Bound Lane S 45° E 14.27'

1990 Wightman & Associates, Inc.

(Corner not described)

Top of Hydrant - S 40° E - 47.4 Edge Concrete Hwy. - E - 2.3' Catch Basin - N 20° E - 53.9' Water Manhole - S 20° E 55.2'

1994 George Mitchell

(Found RR Spike)

Fire Hydrant - S 45° E - 47.34'
Power Pole - S 30° E - 92.43'
Capped Iron - E - 57.38'
10" Poplar S 70° W - 101.68
Centerline N. Bound Lane - E 14±

\*Note: East 1/4 Corner of Sec 12-4-19 & W 1/4 Corner of Sec 7-4-18

Historically have been used as Common Corners

3PAGE 341

LIBER