C	All the second s		appear of the second paper.		og (f	
	·		!	•	RECORDED	
SURVEY PE FFICIAL CORT	THE BERRIEN COUNTY ER GROUP AS THE VER UNDER MICHIGAN ACT 345 OF 1990	LAND CORNE	DUNTY REMONUM R RECORDATION Comment of Act 74, Mic	FRTIFICATE	IV 19 PM 4:48	
For corners BERRIEN C		- - n: Corner		SEN	ICE TRETHEWAY ISTER OF DEEDS I COUNTY, MICHIGAN	
1. Public L	and Survey	T <u>5S</u> R <u>17W</u>	M-12	Register of Deed	is Stamp & File Numb	er
in Section 3. Miscella	***************************************	Γ R Γ R Γ R Γ R		11/19/9 11/19/9	CURNER	A77 \$9.00 A77 FEE \$2.00
4. Lot No_ 5. Private	,Recorded Plat_ Claims			A B C D	E F G H I J K L M	1
under required mentioned rules theref United State a decree of 4 and 5 about the state of the st	irements of P.A. 74, in lines 1 and 2 above ore as required in the ces Department of the I a Court of Law and/or	Michigan P.A. of 19 were in conformance current manual of sure the corner point that the corner point ace with the rules of	the Michigan Board of	4 7 8 5 6 18 17 7 7 8 19 20 9 10 30 29 11		

25

SURVEY & REMONUMENTATION

JAN 12 1888

SECTION

(PLEASE SEE BACK PAGE)

be recorded on this certificate.

monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Rebar in Monument Box 1' East of Center Line Brush Lake Road and 2' South Center Line Stiemke Road. Verified Corner using existing witnesses. This Government Corner was restored with approval of the Berrien County Remonumentation Peer Group of Surveyors October 6 1998.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.


Set 3' long Steel Pipe and 31/2" diameter Berrien County Remonumentation Cap in Monument Box 1' East Center Line Brush Lake Road and 2' South Center Line of Steimle Road.

> Witnesses N45E Found P.K. Nail in NW side of P.P. 38.00 N30W Set Nail and Flasher in SW side 24" Maple 54.55

> S70W Set Nail and Flasher in N side of 36" Maple 59:54 S20W Set Nail and Flasher in SE side 36" Maple 58.95

Corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Surveyor's Michigan License No. 35988





M-12	E 1/4 CORNER SECTION 36,	T5S. R17W	PIPESTONE TWP.
------	--------------------------	-----------	----------------

March 1827	William Broo	kfield Book		f Field Notes			
		e Post	•	1			
		Witnes	ses				
		W. Oak 15	S86 1/2W	19 lks			
		Hickory 8	N8 1⁄2W	35 lks	,		
BCRC	(no dates)						
		Witnes	ses				
		24" Maple	\$20W	57.2'			
	•	NW Cor Hse	S50W	94.7'		·	
		10" Hickory	NE NVA/	40.9'			
		6" Apple 18" Hickory	NW East	75.2 ' 99.4'			
e in the second		,					
Misc Field No	_	Mitnos	606			SURVEY &	
7.5	Iron	Witnes 24" Maple	S20W	57.2'	5	REMONUMENTATION	
		NW Cor Hse	S50W	94.7'			
		10" Hickory	NE	40.9'		JAN 12 1889	
•		6" Apple	NW	75.2'		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
•		18" Hickory	East	99.4'		See that Contains the See I	
e. National and the second se		6" Wild Cherry	S87E	27.2'		SECTION	
J.H. Dewey	Misc Field No I.P.	otes					
		Witnes	ses				
		P.P.	N45E	37.2'			
		Tel Pole	S45E	33.4'			
		Tel Pole	N50W	39.6'			
11/5/1971	D.M.Dreher RLS #13580 Recorded Survey Liber 911 Page 230 & 231 Found Iron Bar						
		Witnes CL Tel Pole	ses N45E	37.7'			
		CL Tel Pole	N45W	40.1'			
•		CL 30" Maple	S5W	57.8'			
		CL 24" Maple	S75W	60.6'			
7/24/1972	Wightman an	d Assoc. R. Gar	rett RLS #16	039 Recorded Su	rvey Libe	er 936 Page 49	
		Witnes	ses				
		Tel Pole	S45E	33.4'			
		Power Pole	N45E	37.2'		•	
	-	Tel Pole	N50W	39.6'			
7/24/1974	Wightman an 1/2" Iron Pipe			039 Recorded Su	rvey Libe	er981 Page303	
		Witnes					
		Utility Pole	S45W	37.85'			
	•	Utility Pole Utility Pole	N45W N45E	33.90' 40.15'			
8/29/1975	Wightman an	•			d Survey	Liber 1006 Page 764	
		(same as a	above)				
10/1/1979	Wightman an	d Assoc. M.R. R	ushlow RLS	# 15191 Survey C	ertificate	•	
	112- 1.1 .	(same as	above)				
1998	Landmark Technologies Alan Bartlett RLS #35988 Found Rebar in Monument Box 1' East of Center Line Brush Lake Road and 2' South of Center Line Steimle Road. Witnesses						
•	-	N45E Fnd P.I		side of P P		38.00'	
				in SW side of 24"	Maple	54.55'	
		S70W Set Na	il and Flashe	in N side of 36" M	aple	59.54'	
		S20W Set Na	il an d Fla shei	in SE side of 36"M	laple	58.95'	