SURVEY & REMONUMENTATION FEB 1 7 1994 COMMISSION For corners in Berrien County: 1. Public Land Survey	LAND CORNER RECORDATION Filing Requirement of Act 74 BERRIEN COUNTY REMO Located In: Corner Code T 55 R 19W G13 T 55 R 19W H13	, Mich. P.A. 1970 NUMENTATION	CURNER \$7.00
in Section S 3. Miscellaneous S Property in Sec. S 4. Lot No, Recorded	T R T R T R T R T R T R T R T R T R T R	Register of I	Deeds Stamp & File Number
I, John G. Kamer , in a field do hereby certify that under requirements in lines 1 and 2 above were in conforma current manual of survey instructions of the Management or by a decree of a Court of Labove were in conformance with the rules Court of Law; established, re-establish expressed below: NOTE: Not more than 4 corners, all on this certificate. A. Description of original monument G-13 1830 government post. Accendicated Garrett stone in Management N 30° E 46.52°. H-13 1830 government post. Accendicated Garrett stone in Management N 1830 government post. Accendicated Garrett stone in Management N 1830 government post. Accendicated Garrett stone in Management N 1830 government post. Accendicated Garrett garagement garagement post. Accendicated Garrett garagement post. Accendicated Garrett garagement garagem	December 2, of P.A. 74, Michigan P.A. of 1970, the corner pence with regulations and rules therefore as the United States Department of the Interior, awand/or that the corner points mentioned in of the Michigan Board of Land Surveyors or ed, monumented, re-monumented, recover in the same town and range, may be a and accessories and/or subsequent resessories: 10" Oak N 58½° E 26 lin on. Box. Accessories: tele pole Sessories: 18" Beech N 46° E 38 lintes, found stone. 1973 W&A Survey 10 W 38.23', PP S 50° W 56.62'. 198 e south 33.0', PK in RR tie wall SPK in PP S 50° W 56.61', PK in RR	required in the Bureau of Land filines 3, 4 and 5 by a Decree of a ered, found as recorded sectoration: ks, 6" Whitewood N 9° W 30° E 41.65', tele pole mks, 15" Beech N 49° W 4 notes IP in Mon. Box. Ac	10 links. 1973 & 1974 S 30° W 41.00' Phone links. 1912 & 1917 excessories Iron Pipe South
G-13 Mon. Box w/ 5/8" Rod. Dist best evidence of corner. C H-13 3/4" Rod in Mon. Box. Dist	und and/or method applied in restoring tances to adjacent corners were restorner common to NW cor 3-6-19. Cances to adjacent corners were restorner common to NA cor. 3-6-19.	asonable and consistent.	
C. Description of monument for corn G~13 Set standard 3' pipe w/b Box in Place of 5/8" Rod and and faithful perpetuation of corner Set Nail w/witness tag in PP Set Nail w/witness tag in S 4 Set Nail w/witness tag in woo Top Hydrant S 27° W 66.86'	is accepted as a careful in the position of the original co S 37° E 41.61' Se 5° W 40.91' Se d post N 32° E 45.61' Se	13 Set standard 10" pip a place of 3/4" rod, and d faithful perpetuation rner. t Nail w/witness tag in t Nail w/witness tag in	of the corner: e w/brass plate in Mon. Box is accepted as a careful of the position of the origin grape post N 25° W 37.90' PP S 58° W 56.88' RR tie Re. wall S 72° E 66.64
Signed by Surveyor's Michigan License No.	27149 LIBER 3 PAGE 57	Date 12-02 FORM APPRÖVED BY MICHIGAR	N STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983