4 3 5	
RATIOCD BY THE BERRIEN COUNTY	,
SURVEY PEER GROUP AS THE	
OFFICIAL CORNER UNDER MICHIGAN	Į
PUBLIC ACT 345 OF 1980	
PUBLIC ACT 345 OF 1980	`
- Charles And	L

3.

Miscellaneous

Property in Sec.

## Berrien County Remonumentation LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

3 39 PM \*94 Aug. 30

REGISTER OF DEEDS A PERRIEN COUNTY MICHIGAN

Located In: Corner Code ## T 5 R 19 Public Land Survey \_\_\_\_ R \_ \_ R \_ \_ R . Τ. 2. Property Controlling in Section

S

Register of Deeds Stamp & File Number

\_ , Recorded Plat \_\_ Lot No. Private Claims \_

, 19 <u>9</u>4 August do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 13

Description of original monument and accessories and/or subsequent restoration:

March 1830 - John Mullett Set Post for 1/4 Section Corner Beech 8 S72W 15 W. Oak 14 South 18

08/30/94

111#2163

Ao6

\* Additional documentation on Sheet #2.

08/30/94

CURNER

49.NO A66

111#2163

STATE REMON FEE \$2.00

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-7 - 1" solid Iron in Monument Box Power Pole B296-105 S36°E 42.0' Power Pole B296-31 S46°W 42.6' Power Pole B279-267 N38°W 42.45' Hydrant N46°E 36.2'

SURVEY & REMONUMENTATION

SEP 1 5 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7 - 1" Pipe/8" Long with 21" Remonumentation Brass Cap in Monument Box Power Pole B296-105 S36°E 42.0' OVER STONE

Power Pole B296-31 S46°W 42.0' Power Pole B279-267 N38°W 42.45'

Hydrant N46°E 36.2'

And is accepted as a careful and faithful perpetuation of the position of the original

Signed by Washi W. Bangar P.S. 31589 Surveyor's Michigan License No. ...

Date \_\_\_ August 29, 1994

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975**

REVISED JAN., 1983

MARCH. 1830 🐇

John Mullett L2. F183

Government Notes

40.10 Set post for 1/4 Sec. Corner on true line Beech 8 S72 W15

W. Oak 14 South 8

UNKNOWN

Berrien County Road Commission

N.W. corner of S.E. headwall 38.8' S.W. corner of N.E. headwall 38.1' 12" Cedar S. 45 W. 34.0'

Telephone Pole N. 45 E. 32.2'

APRIL. 1976

Ron Harner

1" Solid Iron in Monument Box Telephone Pole S. 45 E. 42.0' Telephone Pole S. 45 W. 42.6' Hydrant N. 45 E. 36.2'

AUGUST, 1983

J. Kamer

Fnd. 1/2" Iron Rod with cap (Mon Box) PK in PP N. 45 W. 42.50' PK in PP S. 45 W. 42.80' PK in PP S. 45 E. 42.10'

DECEMBER. 1983

J. Kamer

Found iron in water valve box PK in PP N. 45 W. 42.36' PK in PP S. 45 E. 42.10' PK in PP S. 45 W. 42.65'

MAY, 1994

C. Barger

1" Solid Iron in Monument Box Power Pole B 296-105 S. 36 E. 42.0' Power Pole B 296-31 S. 46 W. 42.6' Hydrant N. 46 E. 36.2' Power Pole B 279-267 N. 38 W. 42.45'