SURVEY & REMONUMENTATION

RATIFIED BY THE BERRIEN COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN

PUBLIC ACT 345 OF 1990

De Care

29-92

corners in

5. Private Claims _

Berrien

1

APR 2 6 1995

RECORDED

BERR CO MANUS SEPONUMENTATION	PROGRAM
-------------------------------	---------

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

DEC 2 1/ 11 AM '94

Bernied Tradering PERSIER OF DECINS


Berrien (County)	•	Located In:	Corner Code ##	"如此相母,其子為母為生於「最后置于0本權		
Public Land Survey		T 6 S. R 17 W.	E-5	12/02/94	111#8049	A99
		T R	·		CORNER	\$7.00
		T R		12/02/94	111#8049	A99
•		T` R			STATE REMON FE	E \$2.00
Property Controlling	9	τ ο ·	• •		•	

in Section _ R Miscellaneous S_ _ T R . Register of Deeds Stamp & File Number Property in Sec.

I, R.L. Harner , in a field survey on November 30 19 94
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

Located In:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



Wightman and Associates December 3, 1991

P.K. nail in power pole N. 45° W. 42.13' P.K. nail in 36" Maple North 30.22'

P.K. nail in 32" Maple S. 60° W. 65.60'

plug in mon. box

C/L road South 0.43

A. Description of original monument and accessories and/or subsequent restoration:

Berrien County Road Commission cap iron North 33.00'

Wightman and Associates August 28, 1974

__ , Recorded Plat _

24" Beech North 31.81'

Surveyor's Michigan License No. 22436

utility pole N. 50° W. 42.19' 20" Maple S. 30° W. 37.63'

plug

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

found plug in mon. box over stone

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

E-5 removed plug and set iron and brass cap in mon. box iron North 33.40' P.K. nail in 36" Oak S. 59° W. 65.64' nail and washer in 36" Oak S. 62° E. 77.15' P.K. nail in power pole N. 59° W. 42.32'

* Accepted as a careful and faithful perpetuation of the position of the original corner.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975