SURVEY & REMONUMENTATION

(),),
RAILFIED BY THE BERRIEN COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER MICHIGAN

IPUBLIC ACT 345_OF 1990

RECORDED

APR 2 6 1995

BERRIEN COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE JEC	2	II 11 M °9
Filing Requirement of Act 74, Mich. P.A. 1970		•

11-29-94 For corners in		RECORDATION CERT	IFICATE DEC 2 11	
Berrien (County)	Located In:	Corner Code ##	REGISTER OF BEEDS REGISTER OF BEEDS REGISTER COUNTY MODIFIED	
Public Land Survey Property Controlling S	T6.S.,R.17.W. T R T R T R			
in Section S 3. Miscellaneous S	TR TR TR		12/02/94 111#804 Register of Deeds Stample File 12/02/94 111#804	Numbe <u>\$</u> 7.00
4. Lot No, Recorded			A B C D E F G H	
5. Private Claims			2 6 5 4 3 3 4 7 8 9 10 10	11 12-
in a field of hereby certify that under requirements in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule Court of Law; established, re-established expressed below:	s of P.A. 74, Michigan P.A. of ance with regulations and the United States Departm Law and/or that the corner p s of the Michigan Board of I	f 1970, the corner points ment rules therefore as required nent of the Interior, Bureau of points mentioned in lines 3, 4 Land Surveyors or by a Decre	in the Land 7 and 5 8 19 20 21 22 e of a	23 24 26 25
NOTE: Not more than 4 corners a	II in the same town and	I range, may be recorded	11	

Description of original monument and accessories and/or subsequent restoration:

Government - post Beech 4" S. 49½° W. 6 links Beech 12" N. 2½° E. 30 links

Berrien County Road Commission

on this certificate.

Wightman and Associates August 28, 1974 plug

18" Locust N. 50° E. 39.06' utility pole S. 55° E. 41.01'

6" Locust South 25.98 Southwest Survey October 24, 1975

cap
iron North 33.00'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Southwest Survey October 24, 1975

mon. box 1' North of C/L road
nail in W. face of pole S. 65° E. 40.95'
P.K. nail in E. face of 18" Walnut South 26.18'
nail in S. face of 15" Walnut N. 80° E. 39.06'
iron North 33.00'
iron North 30.00'
iron North 30.00'
iron North 30.00'
iron North

F-5 found plug in mon. box over stone

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

removed plug and set iron and brass cap in mon. box P.K. nail in power pole N. 32° W. 33.93' P.K. nail in power pole S. 64° E. 40.94' P.K. nail in 6" Maple N. 11° W. 32.33' nail in 24" Oak N. 44° E. 38.38'

*Accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by Surveyor's Michigan License No. ___

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975