	•		x +		
HATTHED BY THE BERRIEN COUNTY				- 	and the second
SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN			11/29/95	11142012	977
PUBLIC ACT 3/15 OF 1990	BERRIEN CO	UNTY REMONUMENTATION	01/27/75 01 11/29/95	AMETER 2	\$9,00
11-22-95		RECORDATION CE		STATE NEEDS	FEE \$2.00
For corners in	Filing Requireme	ent of Act 74, Mich	. P.A. 1970		
BERRIEN Local	ted In:	Corner Code ##		RECORDED	
1. Public Land Survey T 8	SR_20W	A-1		20 0 0. 60=	
Connon to: TTS, RZOW, A13 T-	R	M-13)	light (19 3 39 PH 195	
	R (_	1013	A.	oran e e e Landola de Caração	
2. Property Controlling S T _	R R		投すの おどれ取り	ISTER OF BEEDS OF	ł
3. Miscellaneous S T	R	-		Deeds Stamp & File i	
	R		<u> </u>		-
Lot No, Recorded Plat _ Private Claims			A B	CDEFGH	JKLM
			2 - 6-3	5 4 3 -	
			4 _ /-	8 9 10	1112
i, <u>JOHN G. KAMER</u> , in a field surve do hereby certify that under requirements of P.A.	74, Michigan P.A. of 19	170, the corner points m	entioned 6		
in lines 1 and 2 above were in conformance we current manual of survey instructions of the Unit	ited States Departmen	it of the Interior, Bureau	of Land 7		
Management or by a decree of a Court of Law and above were in conformance with the rules of the	Michigan Board of Lar	nd Surveyors or by a De	cree of a	20 21 - 22 -	23 24
Court of Law; established, re-established, re-	nonumented, re-mont	imented, recovered, t	10 -30-	29 28 27	2625
NOTE: Not more than 4 corners, all in the on this certificate.	e same town and re	ange, may be record	ed 11 12 31-	32 33 34	35-36-
A. Description of original monument and	accessories and/or	eubeenuent restorat	13		
(SEE BACK.)	accessories and/or	Subsequent restorat		THE BY G	
(SEE ENGL.)					
			·		. `
				MAR 27 1996	
			•	COMMISSION	;
 B. Description of corner evidence found a FOUND 1/2" REBAR 1.2' NORTH OF CE 			establishing corner:	·	
- FOUND 172" REBAR 1.2" NORTH OF CE - MEASURED 331'±WEST TO CENTERLINE - OCCUPATION NORTH AGREES WITH CORN	OF GALIEN RIVER.	THIS AGREES WITH	DISTANCE IN 1957 D	EWEY FIELD NOTES.	
- ROAD HAS BEEN NEWLY RESURFACED. - THE ROAD MAY HAVE BEEN BUILT UP.					
		•			
* *		_		•	
C. Description of monument for corner ar	nd accessories esta	hlished to perpetuat	e locating the positio	n of the comer:	
REMOVED 18" X 1/2" REBAR SET MON. BOX. SET A STANDARD 3'		•			
SET MAIL W/TAG IN GUARD POST SOUT SET NAIL W/TAG IN POWER POLE N O	TH 17.46	DRASS FLATE IN MON	ONENI BON 1.2 M C	r character in .	
SET NAIL W/TAG IN 15" HICKORY N 7 SET NAIL W/TAG IN 18" MAPLE N 60°	73° E 51.69' 'W 86.49'				
MEASURED 331'± TO CENTER OF GALL PROBED AND AUGERED 2.0' - 2.5' AN	A GNIF TON GIG ON	Y EVIDENCE OF A PR	REVIOUS CORNER/STON	E/IRON.	
CORNER IS ACCEPTED AS A CAREFUL !	AND FAITHFUL PERPE	TUATION OF THE POS	PITTON OF THIS OKIG	INNU CORNER.	
·	40000 TE. 00	F MICHIGO			
WI	, S. J.	HN G. AMER	1	-	
Signed by		SURVEYOR Flate	11-29-95		
\ 1	27449	No. 27449	FORM APPROVED BY MICH	GAN STATE BOARD OF LAND SURV	EYORS, JAN. 28, 1971
	*, CAED	LANDSURILL	·	· 8	EVISED MAY 14, 1975 REVISED JAK., 1983
LIBER RPAGE 28	5	terata) \$45°			

New Buffalo Township (T 8 S R 20 W) NW Cor. Sec. 6 (A-1)

July, 1829

Lucius Lyon, D.S.

(From East) 80.00 Set Post Cor. to Townships

7 & 8 South Ranges 20 & 21 West

Ash 9 N 56 E 31 Ash 18 N 69 W 21

Nov., 1957 Dec., 1957 J. H. Dewey

Found & Used Cor.

2649.15 to E 1/4 Sec. 1

April 14, 1977

Robert Beland

LCRC Lb. 2 pg 233

Error in Identifying Corner - Does Not Apply

Nov. 21, 1995

'John G. Kamer, Wightman and Associates

NE Cor. Sec 1-8-21

Fnd. 1/2" rebar 1.2' north of centerline Kruger Road

Set nail w/tag in guard post south 17.46'
Set nail w/tag in power pole N 06°W 42.25'
Set nail w/tag in 15" hickory N73°E 51.69'
Set nail w/tag in 18" maple N60°W 86.49'

Occupation N looked ok

Meas. 331+\- to centerline of Galien River

Newly resurfaced road

road may have been built up.