## **SURVEY &** REMONUMENTATION

RATHER BERRIEN COUNTY SURVEY PEER GROUP AS THE APR 2 6 1995 OFFICIAL CORNER UNDER MICHIGAN

\_ , Recorded Plat

RECORDED

COMMISSION LAND CORNER RECORDATION CERTIFICATE NOV 21 10 37 84 194

Filing Requirement of Act 74, Mich. P.A. 1970

Berrien County Remonumentation Corner Code -++

Berried Trederry PERSIER OF DUTIES OF THE PROPERTY OF THE PROPE

<u>_v</u>	(County)	Located III.	Comer Code -/-
1.	Public Land Survèy	T <u>8 S</u> R <u>18 W</u>	F-9
		T R	<u> </u>
		T R	
		T R	
2.	Property Controlling	S R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	<u> </u>

Register of Deeds Stamp & File Number

Robert W. Prestine in a field survey on November 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3 10 11 12 1.3

A. Description of original monument and accessories and/or subsequent restoration:

F-9 South Quarter corner, Section 21, T.8 S; R.18 W; On Indiana-Michigan State Line

111#7352 CORNER

A66 \$7,00

Not set by Government

No record of corner found or set by others

11/21/94

11/21/94

111#7352

A66

STATE REMON FEE \$2.00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Did not find corner - Unable to excavate due to trees - Near fence corner Set corner in line with 6" concrete posts set by W.P.A. in 1938 for Northeast and Northwest corners of Section 10, T.38 N; R.1 E; State of Indiana 853.87 feet East of Northwest corner of Section 10, T.38 N; R.1 E; State of Indiana and 2676.57 feet West of Southeastleorner@of%Section@21; aTa8 S; aRdlanW; aStatedof Michigan which is 28.5 rods West of Southeast corner of Section 21, T.8 S; R.18 W; plus 2206.32 feet West to make 25.5 Acres as called for in Southeast Quarter of Section 21, T.8 S; R.18 W; State of Michigan.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9

4 Lot No

5. Private Claims \_

Set 4" round Berrien County Remonumentation monument

Nail & wit. tag in North side 17" oak S 52° W 8.2'

Nail & wit. tag in South side 14" oak N 78° W 2.4'

Nail & wit. tag in East side 20" maple N 12° E 41.05'

Nail & wit. tag in East side R.R. tie corner post North 1.55'

This position was not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

LIBER

Date November 16, 199/

Surveyor's Michigan License No. \_

18662

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

OF MICHIG

ROBERT W

PRESTINE

LAND

SURVEYOR

18662

RED LAND

3 PAGE 186