REMONUMENTATION

RATIFIED BY THE BERKIEN COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN

PUBLID ACT 345 OF 1990

10-10	3.4600
11/08/	92)
For corners in	,

APR 2 6 1995

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Nov 21 - 10 37 AM '94

Bernice Transcery PEDISTER OF DEEDS GERBIEN FOUNTY WICHIGAN

Berrien County Remonumentation Corner Code ## Located In:

T 8 S R 18 W Public Land Survey R Т Т R **Property Controlling** Ŧ R Т _.R ... in Section Miscellaneous S т R Property in Sec.

Register of Deeds Stamp & File Number

_ , Recorded Plat Private Claims __

I, Robert W. Prestine, in a field survey on November 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Southwest corner, Section 22, T.8 S; R.18 W;

11/21/94

10

111#7352 CORÑER

Aóó \$7.00

On Indiana-Michigan State line

Government wits. gone

Lucious Lyons Nov. 10, 1835 wood post Hickory 13" N 81° W 1.77 chains

Hickory 12" N 18 2° W 2.12 chains

111#7352

966

11/21/94

STATE REMON FEE \$2.00

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Did not find corner-R.R. tie corner post near Set corner as per description of Lakehead Pipeline Company as described in Liber 852, Pages 317, 318 & 319, in line with 6" concrete posts set by W.P.A. in 1938 for Northeast and Northwest corners of Section 10, T.38 N; R.1 E; State of Indina

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-9

Set 4" round Berrien County Remonumentation monument

Nw. cor. house S 7° W 73.7'

Ne. cor. house S 56° E 78.2!

Nail & wit. tag in North side 17" burr oak East 89.7' Face conc. foundation grain bin West 110.1'

This position is accepted as a careful and faithful reestablishment of the position of the original corner.

OF MICH PRESTINE LAND SURVEYOR 18662

Signed by

November 16, 1994

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

REVISED JAN., 1983

Date