RAINISO BY THE BERRIEN	COUNTY	the state of the s		*C.20	المانية الماني المانية المانية	
- JURUSE PERK, GRAIND M	C TLLEX. > ``			RECORDED		
OFFICIAL CORNER UNDER N PUBLIC ACT 345 OF 1		n Country Dominion				
to Came	2/1 LAND CO	n County Remonument RNER RECORDATION C	ation	20-11 05 1	H *95.	
9-14-95	Filing Reg	uirement of Act 74, Mic	h. P.A. 1970	79. H 00 H	V	
For corners in	 ,	,	/(2)	inered Transfer	history	
V Berrien (County)	Located In:	Corner Code =##	1,1	CISTER OF DET	US OF	•
tooding			AE AE AE	iien county M	CHUAN (
1. Public Land Survey	T 8S R 20					
Commento 1785, K19	WAS T R	- /A-5	-	; · ;	i i	
; ;	TR	. (-	, ,	ير الم	
2. Property Controlling	S T R				ar i	
in Section	S T R	<u> </u>			•	
3. Miscellaneous Property in Sec.	S T R S T R		Registe	r of Deeds Sta	mp & File Nu	ımber
r topetty in dec.	. V I n _,		<u> </u>		 -	
4. Lot No, R				4 B C D E	FGHI	
5. Private Claims					F G H I	JKL
	· of		3	— 6— — 5— —	4-1-3-1-	-21-
•			. 4			
, Charles W. Barger				i i	10-	12-
do hereby certify that under req in lines 1 and 2 above were in	uirements of P.A. 74, Michigan F	P.A. of 1970, the corner points n	nentioned	18 17	16	14-12
current manual of survey instru	conformance with regulations actions of the United States De	s and rules therefore as requi partment of the Interior, Burea	red in the iu of Land 7			ÏĬ
Management or by a decree of a	Court of Law and/or that the co	entioned in lines	3,4 and 5	1920	21-22	-2324-
above were in conformance with Court of Law, established, re						1-1-
expressed below:			10	-3029	2827	2626-
	orners, all in the same town	and range, may be record	ded 11		 - - -	
. on this certificate.	, A		12	_31 32 ;	33-34	3536
A. Description of original n	monument and accessories	and/or subsequent restora	ıtion:			
. •		- "				
Jath	1829 L. Lyon	L.2, P.361 Gover	nment Notes	. · ·	Tavay 8	્રિ
•	South on Eas	st bound of Sec 12				ZHON
•		ost in marsh corner	to Secs 12			
. :		arings - no timber :	near	WA	R 2 7 1996	
***	Mostly	y cranberry marsh	. (-		
			•		MMISSIC	JN!
					r Turk	
Description of corner ev	vidence found and/or metho	od applied in restoring or re	establishing corn	er:	D _i	
Rest	ored corner using su	irvev data	09/29	/95	111#7821	A7"
No.	in the second of			CUR	NER	\$ 7. 00
			09/29		111#7821 TC 55750 C	97°, 17°, an or
•				\$1B	TE REMON F	EE WZ.UI
	•					
. ,			· ·			
			<i>"</i>			
·				•		
		,				
	•		·			
,	,					
Telephone and the second secon	nt for corner and accessorie					
M-5 -	- 1" Pipe 36" long w	vith 2½" Remonumena	tion Brass Ca	ip in Monum	ent Box	
OF MC	Set Witness tag ir	SE side of 12^n Ele	n N46°43'38"I	30.77'		
State		SW side of PP-NE of				44.42
CHARLES W. 7		SW side of 42" Wil			1	
BARGER ★ LANDSURVEYOR ★	trou bibe on M K18	tht of Way line S31°	30 23 W 46.	33		
No.	And is accepted as	s a careful and fait	thful perpeti	ation of		
31589		ne original corner.		<u> </u>		
THE SEO LAND CURVE HE			:			
CANAL THIRD STATES	3	•	*, `		,	
			_	,	••	
gned by Marles	W. Barger	Date .	September 2	8, 1995	<u> </u>	· · · · · · · · · · · · · · · · · · ·
urveyor's Michigan License	No. 31589		Photo innovers		NE LAUN ENBUCYAN	. 18M 08 107-
e og er e omernæmt mæetter.			FURM AFFRUYED BT	MICHIGAN STATE BOARD	REVISE	D MAY 14, 1975

LIBER 3PAGE 246

NORTHEAST CORNER SECTION 13-8-20 SOUTHEAST CORNER SECTION 12-8-20

(Three Oaks Township - Avery Road & Buffalo Road)

July 1829

L. Lyon

L.2, P. 361 Government Notes

A result to any of the first

YARIST MERRIN 2HT YE DATE OF

Total Spanned Williams

South on East bound of Sec 12 80.00 Set post in marsh corner to Secs 12 & 13 No bearings - no timber near Mostly cranberry marsh

tina ni 1948 ili mesulmi. Pishim beresalah ini Pishimpania

Sep 1829

L. Lyon

L.2, P. 367 Government Notes

East on R between Secs 12 & 13 79.58 E. boundary 3 links N of post

West corrected bet. Secs 12 & 13

July 1930

Old drawing shows the corner to lie north of the intersection of Avery Road with Buffalo Road. Dimensions show ties to the corner.

Nov 1947

2640' between NE cor 13-8-20 and E 1/4 cor 12-8-20 Notes show similar dimensions proving the corner, although missing now, has perpetuated.

Aug 1995

After probing and digging for iron or stone, iron was set on line with East 1/4 corner of Sec 12-8-20 and SE corner 13-8-20 and SW corner 18-8-19. Ownership and occupation from previous notes were non-existent as agricultural uses prevailed.

LIBER 3PAGE 24"

8381