RATATED BY THE BERRIEN COUNTY		y same		V V 222 - 2008)
SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN	,		11/29/95 11/29/93	11142012	877
PUBLIC ACT 345 OF 1999	BERRIEN	COUNTY REMONUMENTATION		000000	\$9 _# 00
Warrio K Les Com	LAND CORNE	R RECORDATION CERT	FICATE	STRIE RENE FEE	w2.00
// - 2 2 - 95 For corners in	Filing Require	ement of Act 74, Mich. P	.A. 1970		
BERRIEN (County)	_ocated In:	Corner Code ##	RE	CORDED	
1. Public Land Survey Common to: TTS, R20W, A13	T 8S R 20W	A-1	Nov 29	3 39 PH 195	
TIS RZIW MIZ	T R `	M=1	<i>1</i> 3. ·	a the Lawrith and the gr	
	T R			POS BELDS	
	. T R T R			ार्क्स १४ म ्यास्त्रहरू ds Stamp & File Numt) Ar
*	T R		register of Dec		
4. Lot No, Recorded P	lat		——— АВС	DEFGHIJ	K L M
5. Private Claims				5 4 3 2-	
		•	3		
I, JOHN G. KAMER , in a field	NOVEMBE	R 27 , 19 <u>95</u>	4 7 7 5	8	12-
do hereby certify that under requirements of in lines 1 and 2 above were in conformant	of P.A. 74, Michigan P.A. o	of 1970, the corner points ment	ioned	17-16-15-14-	13-
current manual of survey instructions of th	ie United States Departi	ment of the Interior, Bureau of	Land 7		
Management or by a decree of a Court of La above were in conformance with the rules of	of the Michigan Board o	Land Surveyors or by a Decre	eola 💧 🧻	20 21 22 23	24
Court of Law; established, re-established expressed below:	ed, monumented, re-m	nonumented, recovered, tout	10 as	29 28 27 26	25-
NOTE: Not more than 4 corners, all on this certificate.	in the same town an	d range, may be recorded	11		36
• • • • • • • • • • • • • • • • • • • •			13		
A. Description of original monument	and accessories and	i/or subsequent restoration	1:		
(SEE BACK.)	-				P 16 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
					∂ å∜l
				MAR 2 7 1996	
				COMMISSION	
B. Description of corner evidence fo	und and/or method a	applied in restoring or rees	tablishing corner:		
- FOUND 1/2" REBAR 1.2' NORTH C - MEASURED 331'±WEST TO CENTERI - OCCUPATION NORTH AGREES WITH - ROAD HAS BEEN NEWLY RESURFACE - THE ROAD MAY HAVE BEEN BUILT	OF CENTERLINE OF KE LINE OF GALIEN RIVE CORNER LOCATION. ED.	RUGER ROAD.		FIELD NOTES.	
		•			
				•	
			ocation the position of	the corner:	
C. Description of monument for corrections of monument for corrections of the correction of the correc	D 3' X 1" IRON PIPE SOUTH 17.46' N 06° W 42.25' Y N 73° E 51.69' N 60° W 86.49' GALIEN RIVER. 5' AND DID NOT PINE	W/BRASS PLATE IN MONUM O ANY EVIDENCE OF A PREV	ENT BOX 1.2' N OF C	ENTERLINE RD.	
	~0°	OF BRIDE			
	articles.	OF MICHIEVA			
Wat	A WO / L	JOHN G. KAMER AND SURVEYOR Bate	11-29-95		
Signed by Surveyor's Michigan License No.	27140	No. 27440	FORM APPROVED BY MICHIGAN S	TATE BOARD OF LAND SURVEYORS,	IAN. 28, 1971
	28 5	ED LAND SURVEYER			MAY 14, 1975 ED JAH., 1983

New Buffalo Township (T 8 S R 20 W) NW Cor. Sec. 6 (A-1)

July, 1829

Lucius Lyon, D.S.

(From East) 80.00 Set Post Cor. to Townships

7 & 8 South Ranges 20 & 21 West

Ash 9 N 56 E 31 Ash 18 N 69 W 21

Nov., 1957 Dec., 1957

J. H. Dewey

Found & Used Cor. 2649.15 to E 1/4 Sec. 1

April 14, 1977

Robert Beland

LCRC Lb. 2 pg 233

Error in Identifying Corner - Does Not Apply

Nov. 21, 1995

'John G. Kamer, Wightman and Associates

NE Cor. Sec 1-8-21

Fnd. ½" rebar 1.2' north of centerline Kruger Road

Set nail w/tag in guard post south 17.46'
Set nail w/tag in power pole N 06°W 42.25'
Set nail w/tag in 15" hickory N73°E 51.69'
Set nail w/tag in 18" maple N60°W 86.49'

Occupation N looked ok

Meas. 331+\- to centerline of Galien River

Newly resurfaced road

road may have been built up.