SURVEY & REMONUMENTATION

MAR 1 3 1998

SECTION

BRANCH COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

	Filing Require	ment of Act 74, Mich. F	P.A. 1970	
For corners in			STATE OF MICHIGAN	
BRANCH (County)	Located In:	Corner Code ##	Branch County	
GIRARD TOWNSHIP			Recorded	
Public Land Survey	T <u>5 S R 6 W</u>	A - 09		
. , asiis aaiis saive,	T R		10-22-1997 09:55:39	
·	TR			
	T R		Linda Lee Morrison-Mathews	
2. Property Controlling	S T R		REGISTER OF DEEDS	
in Section	S R			
3. Miscellaneous	S T R		Redistaro AQUAZAPassi ALLE	, <u>L</u>
Property in Sec.	S R	1	Hedrarestormeeth Stemb 93316 Without	,
r roperty in Goo.	<u> </u>		.GIRARD TOWNSHIP	
4 Lot No. D	Recorded Plat			
	recorded Flat			<u> </u>
5. Frivate Claims			2 6 5 4 3 2 -	_ -
			3	\perp L
			4 7 8 8 1 1 1	
	7 10 - 8-14 4101107	7 10.07		-12-
	? •i6 a field survey on <u>AUGUST</u> puirements of P.A. 74, Michigan P.A. o		tioned	_
	conformance with regulations and		in the 18 17 16 15 14	13-
current manual of survey instru	uctions of the United States Departn	nent of the Interior, Bureau o	fLand 7	+
	Court of Law and/or that the corner			24
	th the rules of the Michigan Board of e-established, monumented, re-material			
expressed below:	e-established, monumented, re-in-	onamentea, recoverea, rou	10 30 29 28 27 26	25-
•	orners, all in the same town and	d range may be recorded		Ī
on this certificate.	official at the same town and	a range, may be recorded		
on this certificate.		•	12 31 32 33 34 35	-36-
A. Description of original r	monument and accessories and	or subsequent restoration		
c I .O. FIFLDNOTI	FS P CLARK D S 1821	S = UWEST RETWEEN 1	19 & 30. INTERSECTED W. BOUNDARY	
			OAK 13 EAST 65, W OAK 12 S31E 54	11
BENNETT, 1872: 1		(3203. 17 d 30. H	ONR 13 ENGT 03, # ONR 12 831E 34	,
	LS, 1961 SURVEY: "IRON'	1		
			DVISED ME HE MADE A THOROUGH SEARC	٩u
	S CORNER & SET 1/2" IRC			711
			RON DURING BRIDGE REBUILDING	
PROJECT		SNOMENT BOX OVER TI	NON DURING BRIDGE REBUILDING	
. 1100201	•			
Description of corner ev	vidence found and/or method ap	oplied in restoring or rees	tablishing corner:	
ON THIS DATE I	FOUND THE IRON SET BY F	ROGERS, NOW IN A MC	ONUMENT BOX; TOP OF IRON IS NOW 15	5 11
DEEP. BOX NOW I	HAS RINGS ADDED TO TOP	OF BOX, (COVER IS	MISSING).	
SET 1/2" × 24"	STEEL REBAR, SO THAT	BRANCH COUNTY REN	MONUMENTATION CAP IS OVER OLD ROD);
ADDED EXTRA RING	G TO BRING BOX TO ROAD	SURFACE.	•	
		•		
AND IS ACCEPTED	AS A CAREFUL AND FAITH	HEUL PERPETUATION (OF THE POSITION	
OF THE ORIGINAL	CORNER.		_ \	
			~ ?	
		•	Tai	`
			Fase 1	١ .
			<u> </u>	
			(人) 転送。	`
C. Description of manuma	nt tar carner and acceptaine of	stantiehad ta narnetuate k	ocating the position of the corner- \mathbb{R}^{2}	.1

1/2" x 24" STEEL REBAR, WITH BRANCH COUNTY REMONUMENTATION CAP:

S 65 E 47.80' - NW CORNER OF TELEPHONE PEDESTAL.
S 75 E 43.20' - SPOTTER ON TOP OF E. WOOD POST OF GUARD RAIL.
N 60 E 85.60' - SCS TAG ON SOUTH FACE OF P. POLE.

S 30 W 52.20' - SPOTTER ON TOP OF WOOD GUARD RAIL POST @ NW CORNER OF BRIDGE.

NORTH 49.30' - S. FACE OF RR-TIE ANCHOR POST (FENCELINE RNG NORTH).

EDWARD R REED' OPESSION

AUGUST 7, 1997

EDWARD R. REED, P.S. Surveyor's Michigan License No.