

FEB 0 8 1899

SECTION

BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE iber 10003 Page 1247 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	STATE OF MICHIGAN
BRANCH COUNTY Located In: Corner Code #	Branch County Recorded
GIRARD TWP	
1. Public Land Survey T 5 S R 6 W M-1	12-07-1998 13:53:20
T R	Linda Lee Morrison—Mathews
T R	REGISTER OF DEEDS
2. Property Controlling S T R	D. M. and D. Marian C. Ella Marian
in Section S	Register of Deeds Stamp & File Number PTED BY THE BRANCH COUNTY
SURV	EY PEER GROUP AS THE OFFICIAL
	1990 AT A MEETING HELD ON
Property in Sec. S T R	E.K. Keed Co. Kep.
	E.R.REED
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J K L
	z 6 5 4 3 2 1
	3
I, <u>EDWARD W. REED</u> , in a field survey on <u>JULY 14</u> , 19 98 do hereby stat	e]
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines and 2 above were in conformance with regulations and rules therefore as required in the curren	t 6 18 17 16 15 14 13
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3	
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as	y 8 19 20 21 22 23 24
expressed below:	9
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	10 30 29 28 27 26 25
on this certificate.	11 32 33 34 35 36
CORNER COMMON TO SECTION 6, BUTLER TWP., BRANCH COUNTY,	13
SECTION 1, GIRARD TWP., BRANCH COUNTY SECTION 36, TEKONSHA TWP., CALHOUN COUNTY	
SECTION 31, CLARENDON TWP., CALHOUN COUNTY	
A. Description of original monument and accessories and/or subsequent restoration:	
1825: WM. BROOKFIELD, DEPT. SURVEYOR - CORNER SET	
1907: CHAS. HAMILTON, CO SURVEYOR - FOUND DRAIN TILE FILLED WITH (
BROKEN BRICK, BUT NO STONE, RECORDED IN LCRC # 198, SET 3/4" IRON & TILE	
B. Description of corner evidence found and/or method applied in restoring or reestablish	ning corner:
FOUND 3/4" X 18 CAPPED IRON WITH GLASS, BRICK AND TILE	
C. Description of monument for corner and accessories established to perpet	uate locating the position of the corner:
SET ½" X 18" REBAR IRON WITH REMON CAP IN CI-MONUMENT BOX 4" BEL	telling and the control of the co
TEL PED N 76 E 87.7' 2" CEDAR S 11 E 102.5'	TO OF MICHIE
22" CHERRY TREE S 65 E 85.8' TO CENTER	EDWARD A
2" X 2" ANGLE IRON POST N 27 E 30.7' TO FACE	W. REED
	SURVEYOR
AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION	NO. 33985
OF THE POSITION OF THE ORIGINAL CORNER.	33985 CAND SUFF
Signed by Signed by	Date <u>NOV. 4, 1998</u>
EDWARD W, REED	·
Surveyor's Michigan License No. 22005	