## COLLAR REMONUMENTATION

APR 2 6 1995

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON AT A MEETING

Rep

COMMISSION BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970


1	Ē	r .	~~	rn	Δ	rs	in
ı	-0	r	CO	ип	IE.	rs	111

roi comers in			
Branch (County)	Located In:	Corner Code =##	STATE OF MIGHTON
UNION TOWNSHIP 1. Public Land Survey	T _5_SR7_W T R T R		STATE OF MICHIGAN Branch County Recorded 12-28-1994 15:01:02
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R S R S T R S T R R S T R R S T R R R S T R R S T R R S T R R S T R R S T R R S T R R R S T R R R R		Linda Lee Morrison-Mathews REGISTER OF DEEDS Register of Deeds Stamp & File Number
	Recorded Plat		Liber DEFGHIVES
do hereby certify that under recin lines 1 and 2 above were in current manual of survey instrumanagement or by a decree of above were in conformance will Court of Law; established, expressed below:	, in a field survey on December quirements of P.A. 74, Michigan P.A. no conformance with regulations and uctions of the United States Departs a Court of Law and/or that the corner the the rules of the Michigan Board or re-established, monumented, re-rorners, all in the same town and corners, all in the same town and the same town and the rules of the same town and the same town and the same town and the same town and the rules of the rules o	of 1970, the corner points mention of rules therefore as required in tment of the Interior, Bureau of Li er points mentioned in lines 3, 4 ar of Land Surveyors or by a Decree monumented, recovered, found	ned the and 7 19 20 21 22 23 of a
Corner common to Township, Branch 1825: : Brookfie 189_: Hamilton, 1982: McMachen, 1985: Carr, found	County, Michigan. ld, corner set found corner, with found iron pipe 15	22, and 23, Town both US witness below road surfa	5 South, Range 7 West, Union trees ace, set 1/2" capped iron

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" iron capped #16935. Nothing found below iron.

Reset 1/2" x 18" rebar, remonumentation cap and cast iron box flush with road surface



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

1/2" rebar as noted above:

l/2" rebar as n	oted above:
-----------------	-------------

N 60 E 61.08'

utility pole

S 20 W 78.0'

NE corner of house

N 72 W 105' telephone pole

60 W 88.71

54" maple

And is accepted as a careful and faithful perpetuation of the position of the original corner.

<u>pecember 14, 1994</u> \_ Date \_ Signed by EDWARD REED FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975 Surveyor's Michigan License No. .

REVISED JAN., 1983