RE. ....

FEB 0 2 2000

## BRANCH COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

T A 10 10 10 10 10 10 10 10 10 10 10 10 10	Filing Requirement of Act 74, Mich. P.A. 1970		
	· · · · · · · · · · · · · · · · · · ·		
mer from many and many the fi	•		

SECTION			
_		STATE OF MICHIGAN	
For corners in		Branch County	
BRANCH COUNTY_	Located In: Corner Code #	Recorded	
BUTLER TWP	_ Located iii.	و سو پوښې و د پېښېږيو پېښو پېښو	
50,22.		12-30-1999 11:00:54	
1. Public Land Survey	T <u>5S</u> R <u>5W</u>	1 South Charles No. 1 South Reports	
	TR	Linda Lee Morrison-Math	
-	TR	regist <b>e of Otas</b> e	עכעו
	TR		
2. Property Controlling	S T R		
<del>_</del>		Register of Deeds Stamp &	File Number
in Section	<u>\$</u>	•	
	TR	and the second	· ACHNTV
3. Miscellaneous	S	SURVEY PEER GROUP AS THE	
_	TR	CORNER UNDER MICHIGAN PUBLI OF 1990 AT A MEETING	CACT 345 HELD ON
Property in Sec.	S	DEC. 07. 1999	
·	TR	E.R. Reed	P. S
		E.R. REED	*
4. Lot No, Rec	corded Plat	÷ . }	
		ABCDEFGHI	JKL
5. Private Claims		1	
		2 - 6 - 5 - 4 - 3 - 1	
I, EDWARD W. REED , in	a field survey on OCT. 21. , 19 99 do hereby state that	3	
under requirements of P.A. 74	1, Michigan P.A. of 1970, the corner points mentioned in lines 1	4 - 7 - 8 - 9 - 10	1112
and 2 above were in conformat	nce with regulations and rules therefore as required in the current		
	of the United States Department of the Interior, Bureau of Land	5	<del></del>
	f a Court of Law and /or that the corner points mentioned in lines	6 -18 -17 -16 -15	1413_
	ormance with the rules of the Michigan Board of Land Surveyors	7	
	Law; established, re-established, monumented, recovered, found		
as expressed below:		8 -19 -20 -21 -22	
NOTE: Not more than 2 com-	and in the same taken and some most be reported	9	
	ers, all in the same town and range, may be recorded	10 30 29 28 27	26 <u>2</u> 5
on this certificate.			
COLUMN ASSESSMENT OF THE COLUMN ASSESSMENT OF	E OFOTION OO	1	
SOUTHWEST CORNER O		12 31 32 33 34	—35——36— !
NORTHWEST CORNER O	F SECTION 31	13	
A. Description of original	monument and accessories and/or subsequent		
restoration:			• •
			3
	D.S., SET GIRARD CORNER		
1826: ROBT. CLARK, JR.	., D.S., SET BUTLER CORNER, 44 LINKS SOUTH OF G	IRARD CORNER	
•			with the second
B. Description of corner ex	vidence found and/or method applied in restoring or reestabli	ishing corner:	
FOUND 4" X 6" STONE 1	18" DEEP		
SET REMON CAP ON 1/2"	X 8" REBAR OVER STONE IN CAST IRON MONUMEN	IT BOX 4" BELOW GRAVEL F	ROAD
SURFACE		.,	
001117102			
C Description of manuma	ent for corner and accessories established to perpetuate	a locating the position of the	corner:
		e locating the position of the	corner.
	EMON CAP IN CAST IRON MONUMENT BOX		
	·		
S65E 43.46'	SPIKE N SIDE ROUND WOOD ANCHOR P		<b>2.</b>
N30E 46.58'	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS	T OF HICH	
	SPIKE N SIDE ROUND WOOD ANCHOR P	T OF HICH	
N30E 46.58'	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS	T OF HICH	
N30E 46.58' N15W 67.97'	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS	T EDWARD W. REED	
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18'	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11	T CHAICA T EDWARD W. REED LAND	
N30E 46.58' N15W 67.97' S85W 63.88'	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE	T T EDWARD W. REED LAND SURVEYOR	
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD	T CHAICA T EDWARD W. REED LAND	
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION	T EDWARD W. REED LAND SURVEYOR NO. 33985	500
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION	T EDWARD W. REED LAND SURVEYOR NO.	1000
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION	T EDWARD W. REED LAND SURVEYOR NO. 33985	SOLUM
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION	T EDWARD W. REED LAND SURVEYOR NO. 33985	500
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S AND IS ACCEPTED AS A COOF THE POSITION OF THE	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS TOP CENTER OF SQUARE ANCHOR POS SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION	EDWARD W. REED LAND SURVEYOR NO. 33985 LAND SUR	100 mg
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S  AND IS ACCEPTED AS A COOF THE POSITION OF THE	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS' TOP CENTER OF SQUARE ANCHOR POS' SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION ORIGINAL CORNER.	T EDWARD W. REED LAND SURVEYOR NO. 33985	500
N30E 46.58' N15W 67.97' S85W 63.88' NORTH 30.18' 19' S AND IS ACCEPTED AS A COOF THE POSITION OF THE	SPIKE N SIDE ROUND WOOD ANCHOR P TOP CENTER OF SQUARE ANCHOR POS' TOP CENTER OF SQUARE ANCHOR POS' SPIKE N SIDE POWER POLE GIRARD CORNER M-11 OF CENTERLINE E-W GRAVEL ROAD CAREFUL AND FAITHFUL PERPETUATION ORIGINAL CORNER.	EDWARD W. REED LAND SURVEYOR NO. 33985 LAND SUR	Sold State of the