SURVEY & REMONUMENTATION

MAR 1 3 1998

BRANCH COUNTY REMONUMENTATION CORNER

SECTION

LAND CORNER RECORDATION CERTIFICATE

For corners in	riling Requireme	III OI ACE 14, MICIE F.A. 1	STATE OF MICHIGAN
BRANCH	Located In:	Corner Code #	Branch County Recorded
(County) QUINCY TWP. 1. Public Land Survey	TR	F-11	10-22-1997 09:57:56 Linda Lee Morrison-Mathews REGIST BOOMS S Page 0175
	TR TR		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plants	at		A B C D E F G H I J K L M 2 6 5 4 3 2 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
In a field survey on <u>SEPTEMBER 3</u> , 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		4	
NOTE: Not more than 2 corners, all on this certificate.	In the same town and rang	e, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: 1825: WM BROOKFIELD, DEPT. SURVEYOR - CORNER SET 1923: E.L. MINER, CO. SURVEYOR - UNABLE TO LOCATE POST, RESET CORNER ON LINE AT 2640 WEST OF SECTION CORNER, SET A FORD DRIVE SHAFT SURROUNDED BY SMALL STONES. 1927: E.L. MINER TIED PLAT OF "CEDAR POINT SUBDIVISION" TO CORNER E.R. REED TIED PLAT OF "SILVER DOLLAR CIRCLE" TO CORNER E.R. REED TIED PLAT OF "BOWERMAN'S LANDING" TO CORNER 1976: E.R. REED, CO. SURVEYOR - FORD AXLE SHAFT OBLITERATED BY ROAD CONSTRUCTION, RESET 3/4" IRON BY RETRACING SURVEY OF MINER'S 1923 SURVEY. RECORDED IN LCRC # 184 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 3/4" SOLID IRON ROD AS DESCRIBED IN LCRC # 184			
C. Description of monument for SET ½" X 18" REBAR IRON WIT			ing the position of the corner: WITH ROAD SURFACE
TAG ON N. SIDE 36" MAPLE, SE NAIL & WASHER E. SIDE 8" MA NAIL & WASHER N. SIDE 14" T NAIL & WASHER S. SIDE 6" MA	APLE, N50W 46.45' WIN WALNUT, S81W 8	33.71'	
AND IS ACCEPTED AS A CARE	FUL AND FAITHFUL P	ERPETUATION OF THE F	POSITION OF THE ORIGINAL CORNER
Signed by Signed by	u W. Kry		Date <u>SEPTEMBER 3, 1997</u>
EDWARD W. REED Surveyor's Michigan License No.		EDWARD W. REED LAND SURVEYOR NORM APPROPERBY 33985	MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28 REVISED MAY 14,1975

SED LAND SURF