**SECTION** 

For corners in

expressed below:

on this certificate.

## BRANCH COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN Branch, County Recorded

BRANCH (County) MATTESON TWP.		Located In:			Corner Code ##					09-26-2000 10:17:59										
										Linda Lee Morrison-Mathews										
1.	Public Land Survey	·	T	S R 8 _ R _ _ R _ _ R			1 - 0	7	- -			REG	ĪST	ER	OF	DEE	:Sor :DS	t11 <del>,</del>	<b>3</b> W 16	/WS
2.	Property Controlling in Section	s s	T	R R					-	Lil	)er	Ũ	O(	)( <u>)</u>	4	Pas	e (	]	ij:	<u> </u>
3.	Miscellaneous	s	T	_ R					_	Regist	er o	of D	eed	s St	amr	. & I	File	N	mhe	,
	Property in Sec.	s	T	_ R	<del></del>													110		· 
	Lot No.									<del></del>	A	В	Ci	) E	F	G	н	1,	JΚ	L
5.	Private Claims				<del></del>	<del> </del>		w		;	,[_	Ţ	Į	<b>~</b> ·	Ţ	$\top$	Ţ			Ţ
										-			Ϊį	$\top$	- ĵ -			1	ĺ	_ -
							•					Ţ			Ţ		Ţ	Π.	Ţ	
, 8	DWARD R. REED, P	.S <sub>in a fic</sub>	eld survey o	ìπ	APRI	L 25		XX	2000			í	Ϊ		- 9 			Τ'	i	—12- 
do in	hereby certify that under re lines 1 and 2 above were rrent manual of survey inst	quiremen in conforn	ts of P.A. 74, nance with	Michiga regulation	an P.A. of ons and	1970, th	e corne erefore	rpoints r as requi	nentioned ired in the			18—	17	,	-16-		-15	-1	4-	13-
	nagement or by a decree of				•			•						Ţ			Ţ	Τ,		

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

MATTESON TWP., T6S, R8W

12

1825: G.L.O. FIELDNOTES OF JOHN MULLETT, D.S.: "SET POST COR. SEC'S 13 & 24".

1969: G.E. ANDERSON, MSHD: "FOUND BROKEN TILE AND STONE CLUSTER 2' BELOW THE GRAVEL SURFACE OF PARHAM RD. IN LINE WITH A FE. TO THE WEST. RAISED TO 1 BELOW THE SURFACE WITH A 3/4"x32" PIPE IN MON. BOX. PLACED BROKEN TILE IN MON. BOX."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND THE PIPE IN THE MONUMENT BOX, 18" BELOW ROAD SURFACE. SET BRANCH COUNTY REMON-UMENTATION CAP ON 1/2"×18" REBAR, IN CONCRETE IN PIPE. ALL IN C-1 MONUMENT BOX.

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE

ORIGINAL CORNER.

ACCEPTED BY THE BRANCH COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON AUG 9, 2000

Å. E.R. REED CO. Rep.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: BRANCH COUNTY REMONUMENTATION CAP, ON REBAR, IN PIPE IN CONCRETE, IN C-1 MONUMENT BOX:

NORTH 30 EAST 56.91' - NEAR FACE OF POWER POLE.

NORTH 65 EAST 18.5' - TOP CENTER, EAST END OF CMP DRAIN CULVERT.

NORTH 50 WEST 16.9' - TOP CENTER, WEST END OF CMP DRAIN PIPE CULVERT. NORTH 101.1' - C/L STATE HWY. M86 PAVEMENT (ON N-S SECTION LINE).

NORTH 52 WEST 98.8' - TOP, SOUTH END CMP CULVERT.

7437

EDWARD R REED ROFESSIONAL SURVEYOR HO. 7437 HOLEBRACON

Signed by .

EDWARD R. REED.

Date <u>APRIL 25, 200</u>0