	ALENEY &	
	MOTTATION	BRANCH COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE
For corners in	14 N O O 1000	Filing Requirement of Act 74, Mich. P.A. 1970

BRANCH Count COWNISSION ocated In: Corner Code ##	Liber UUUUJ Page UUJ (STATE OF MICHIGAN
OVID TWP.	Branch County
1. Public Land Survey T 7S R 6W I-5	Recorded
T R	
T R T	09-28-1995 10:22:04
2. Property Controlling S T R	
in Section S T R	Linda Lee Morrison-Matheus
3. Miscellaneous S T R	REGISTER OF DEEDS Register of Deeds Stamp & File Number
Property in Sec. S T R	register of Deeds Stamp & File Rulliper
	•
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
5. Private Claims	
•	
	3
Edward M Dood Type 10 05	4 - 7 8 - 1 - 9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
Edward W. Reed , in a field survey on June 19 , 19 95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention	ned 5
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in	the 6 18 17 16 15 14 13
current manual of survey instructions of the United States Department of the Interior, Bureau of Li	and 7
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 ar	nd 5 8 19 20 21 22 23 24
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Court of Law; established, re-established, monumented, re-monumented, recovered, found	ora 9
expressed below:	10302928272625
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	11
on this certificate.	12 3, 32 33 34 35 36
	13
A. Description of original monument and accessories and/or subsequent restoration:	
CORNER COMMON TO SECTIONS 10, 11, 14, & 15, T7S, R6W, OVID T	WP., BRANCH COUNTY, MI.
1825: Wm. Brookfield-set corner	• •
1869: Survey by Bennett, Deputy County Surveyor	
1873: Field notes of unknown surveyor-stone well	planted
1948: H. L. Russell-survey tied to corner	
1963: Russell Roon, Survey Chief, M.S.H.D., found 7/8" pin	flush with road surface
1975: Ross Ruckel-survey tied to corner L.C.C.R. #164 - 1/2	" iron pipe in monument box
1978: F. J. Cutcher, L.C.C.R. #243 - 3/4" pipe in monument	pox
1991: E. R. Reed-survey tied to corner	
the state of the s	bliching corner
B. Description of corner evidence found and/or method applied in restoring or reestate	county
Found 3/4" iron pipe in monument box	THE BRANCH OFFICIAL
Set 1/2" rebar iron and remonumentation cap	ACCEPTED BY GROUP AN PUBLIC ON HELD ON
	SURVER UNDER THE MEETING
	of 199-13-00 Co (Co)
	E.K.Essay
•	
·	
	•
	asian sha position of the gorner
 Description of monument for corner and accessories established to perpetuate loc 	tating the position of the corner.
In centerline N-S road	
2' N of centerline of E-W road	
S40°E 73.10°-NW corner of house	A STATE OF THE STA
N60°E 44.84'-SW corner of telephone pedestal	A Salar Company of the Salar
N38°W 48.9'-to E face of telephone pedestal	· · · · · · · · · · · · · · · · · · ·
and the complete and a second control of the first	
And is accepted as a careful and faithful	🚦 🧗 SULVENOUS 🦸 👸
perpetuation of the position of the original corner.	\$ 100 Jan 1988
A	
	The state of the s
	The state of the s
Man 112 Kar	June 19, 1995
Signed by Almy William Date Date	- Letter de la company de la c
Edward W. Reed 33985 Surveyor's Michigan License No. 33985	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
——————————————————————————————————————	REVISED MAY 14, 1975