## APPROVED Pate 11-12-96 CALHOUR JOURTY REMONUMENTATION.

## CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

For corners in

Private Claims

Filing Requirement of Act 74, Mich. P.A. 1970

19 NOV 96 1:57 P.H.

Calhoun (County) Clarence To	Located In:	Corner Code ≠≠	ANNE B. NORLANDER CLERK - REGISTER OF DEEDS
Public Land Sur		<u>K-1</u>	LIBER 1899 PAGE 605
Property Contro in Section	S R		
<ol><li>Miscellaneous Property in Sec.</li></ol>	S T R S T R	-	Register of Deeds Stamp & File Number
4. Lat No	, Recorded Plat		


Donald J. Davis in a field survey on October 25, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Survey in 1825 by Sibley. Resurvey in 1889 by Gifford, tile set.

Consumer Power survey found 1-1/8" iron in 1967. South end of 48" CMP S 60° E 43.00' North end of 48" CMP N 60° E 48.55'



Clarence Twp.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 48" CMP and used for resetting location. Excavated and found no evidence of iron or tile. Set tile corner location using the witnesses.

SURVEY & REMONUMENTATION

MAR 2 1 1997

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Harrison monument 4" under surface of road.

South end 48" culvert S60°E 43.00' North end 48" Culvert N 60° E 48.55'

Nail & Tag 14" Elm N 10° W 24.00' Nail & Tag 14" Oak S 75° W 61.29'

Nail & Tag 18" Maple S 75° E 65.50'

Nail & Tag 8" Quad Maples N 80° W 52.32'

WILLIAM CONTRACTOR MATE OF MICHIGAN DAVIS 25, 1996

Dônald J. Donald J. Davis Surveyor's Michigan License No

17617

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983