Date 11-12-96 CALHOUM ADDUTY REMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 4070

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

19 NOV 96 1:57 P.H.

Fo	or corners in	riling Hequi	ement of Act 74, Mich. P.A.	1970 17 RUY	70 Ital rene
_	Calhoun		1	VINE	B. NORLANDER
	(County)	Located In:	Corner Code ##		REGISTER OF DEEDS
1.	Public Land Survey	Т <u>1SR 4W</u> ТR ТR	K-2	LIBER 1899	PAGE 606
2.	Property Controlling in Section	S T R S T R			
3.	Miscellaneous	S . T R			
	Property in Sec.	S T R S T R S T R		Register of Deeds S	tamp & File Number
4.	Lot No	Recorded Plat			
5.	Private Claims			A B C D	E F G H I J K L M
				3	3-2-0-1-
, E	Oonald J. Davis	_ , in a field survey onO	ctober 16 96	4 - 7 - 8 - 1	9 10 11 12
do	hereby certify that under r	requirements of P.A. 74, Michigan P.A	of 1970, the corner points mentione	d 5	-
in	lines 1 and 2 above were	in conformance with regulations a	nd rules therefore as required in th	բ ^Մ 1817վ	—1 6 —15——14——13—
Ma	rrent manual of survey ins inagement or by a decree (structions of the United States Depa of a Court of Law and/or that the corn	tment of the Interior, Bureau of Lan- er points mentioged in lines 3, 4 and	- [
abo	ove were in conformance :	with the rules of the Michigan Board	of Land Surveyors or by a Decree of	a [1920]	-21222324
Ço	urt of Law; established, pressed below;	re-established, monumented, re-	monumented, recovered, found a	s ⁹	
		comers, all in the same town a	nd range may be recorded	10 30 29	28 27 26 25
	on this certificat		and the second of the second o	12 31 32	-33 -34 -35 -36
A.	Description of origina	Il monument and accessories an	d/or subsequent restoration:	13	
		in 1825 by Sibley.	er er eddesyssem restoration.	Cla	rence Twp.
	Resurvey by Gif	ford in 1889, tile set Consumers Power Co. in E 17.05'	1967, 1" iron placed h	y tile.	SURVEY &
		corner South 37.70'		,	• •
					MAR 2 1 1997
В.	Description of corner	evideпce found and/or method	applied in restoring or reestablis	shina corner:	COMMISSION
		sses and was told by Ca			on was removed
	Reset point loc	ation from witnesses.	Excavated and found no	evidence of co	mer.
		oint location to reset			
	P P	ome acceptant to repet	COLUET.		
			(· · · · ·	
~	Daniel de la company				
J.		ent for corner and accessories		ng the position of the	corner:
		nument in monument box. terline of bituminous s			
	14" Cherry stum	p S 42° W 44.65'	WHITE OF MICH	No.	
	I Beam fence co	rner South 37.70'	The Carrier	W	
	Nail & Lag 12" Nail & Tag 10"	Red Oak S 25° W 32.50' Hickory North 35.90'	# DONALD J.	*	
	Nail & Tag 8" H	ickory N 40° W 49.35'	DAVIS PROFESSIONA	i i i i i i i i i i i i i i i i i i i	
		y -: 10 11 17107	# - 4 41151151151	` • ro⊤ 55	
			No.	JE E	
	\cap	\ \ \	3 65 . 1/61/	gunner er 25, 1996	
	1()	11/21) -	MOFESSION	INNIE.	
Sigi	ned by Donald	ud X Namo	Dale Dale	er 25, 1996	

Signed by Donald J. Davis 17617

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983