## CALHOUN COUNTY REMONUMENTATION

## **LAND CORNER RECORDATION CERTIFICATE** Filing Requirement of Act 74, Mich. P.A. 1970

Fo	er corners in	Filing Require	Filing Requirement of Act 74, Mich. P.A. 1970				1Q	Me	IJή	/ F	N	EA		Ó	N.	
Calhoun		Located In:	Corner Code ##						LHOU Rec							
	Sheridaff"Twp.								RCL	unı	UC.D					
1.	Public Land Survey	T 2 S R 4 W	J-13				22	SEF	P 95	ī 1(	):()	0 A.	М.			
		T R T R T R			ANNE B. NORLANDER CLERK - REGISTER OF DEEDS											
2.	Property Controlling in Section	S T R S T R														
3.	Miscellaneous Property in Sec.	S T R S T R		Regi	ster	of [	)ee	ds :	Sta	mp	&	Fite	N	μm	ber	
	· ·	Recorded Plat			A	В	С	D	E	F	G	н		J	к	
Э.	Private Claims				- 1	1	1		1	1	ì	[	- 1	- 1	- 1	

Donald J. Davis , in a field survey on August 17, <sub>19</sub>95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration:

Original survey in 1825 by Lyon. 6" Burr Oak N 45° E 72 links. 15" Burr Oak N 48½° W 139 links.

No record of corner found or used.

All plats in City of Albion referenced to each other and none to corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Set point on line at midpoint between SE and SW corner of section.

Excavated in centerline of Michigan Avenue and found no evidence of corner.

Accepted midpoint as location of restoring corner point.

يمير او الداري الداري . المستقدار و او او اوسياليية FEMONUMENTATION

LIBER 1822 PAGE 29

10

11

FEB 2 2 1996

## COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Berntsen monument in monument box, falls on centerline of Michigan Avenue.

Donald J. Davis

NE corner of house foundation S 30° W 70.46' NW corner house foundation, #512, S 15° E 83.25' Face of east 6" steel gate post N 45° W 71.85' Nail & Tag light pole N 45° E 56.17'

Date <u>September 15,</u>

General TE OF MICHIGAN STATE OF MICHIGAN PROFESSION NO.
17617
5, 190 PROFESSION AL MENTE MATERIAL MATERIAL

Surveyor's Michigan License No. (17617

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975