APPROVED

Date 12-16-97 RRC CALHOUN COUNTY

DEMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE STATE OF MICHIGAN CALHOUN COUNTY

	Filing Requ	irement of Act 74, Mich. P	.A. 1970 RECORDED
For corners in			19 DEC 97 2:38 P.H.
CALHOUN	Located In:	Corner Code #	17 DLG 77 Zedo Felle
(County) MARENGO 1. Public Land Survey	T <u>2S_R_5W_</u> TR TR	<u>l-8</u>	ANNE B. NORLANDER CLERK - REGISTER OF DEEDS LIBER 1985 PAGE 526
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat		ABCDEFGHIJKL)
			2 - 6 - 5 1 - 3 2 1 -
I. MICHAEL A. GROAT , in a field survey on DECEMBER 2 , 19.97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			bove street 5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9
on this certificate.			10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 11 12 31 32 36 36 36 36 36 36 36 36 36 36 36 36 36
A. Description of original mo	onument and accessories and	l/or subsequent restoration:	
LUCIUS LYON, DEPUTY SU OAK, 13", N8°E, 36 LKS.	RVEYOR, 1825, SET POST,	B. OAK, 9", S6°W, 13 LKS., B	
J.M. GIFFORD, 1889, FOUN	D STUMP OF BEARING TRE	E, CORNER FELL ON SW SII	DE OF 24" OAK
D. DEKEYSER, MARCH 2, 1 78.3' NORTH OF CENTERLI	98?, FOUND 1-1/2" IRON IN NE OF EAST BOUND 1-94, 2	MON. BOX, 1' BELOW GRAVI 8.41' SOUTH OF SURVEY CE	EL IN LINE WITH FENCES NORTH AND SOUTH. NTERLINE OF 1-94.
B. Description of corner evi	dence found and/or method a	pplied in restoring or reestablis	hing corner:
FOUND 1-1/2" IRON IN MON ACCEPTED THE POSITION	I. BOX CALLED FOR BY DEF OF THE IRON AS THE BEST	KEYSER. NO FIRECLAY COU TLOCATION OF THE ORIGIN	ILD BE FOUND DUE TO CONSTRUCTION OF 1-94. AL CORNER.
C. Description of monument	for corner and accessories es	tablished to perpetuate locatin	
SET A BERNTSEN MONUME NORTH, FACE OF ANGLE IF EAST, FACE OF CENTER SI SOUTH, FACE OF ANGLE IF S65°W, MOST NORTHERLY 28.41' SOUTH OF SURVEY OF 78.3' NORTH OF CENTERLIN	RON FENCE POST, 96.31' UPPORT OF 22-1/2 MILE RO RON FENCE POST, 153.33' ' POST OF ROAD SIGN, 319. CENTERLINE OF I-94 NE OF EASTBOUND LANE	AD BRIDGE, 1312.75'	MICHAEL A. GROAT PROFESSIONAL & SURVEYOR No. 39079
Signed by		Date <u>DECEMBE</u>	
Surveyor's Michigan License I	vo. <u>39079</u> S	URVEY &	

APR 0 7 1998

REMONUMENTATION

FORM APPROVED BY INICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 22, 1971 REVISED MAY 14,1975 REVISED JAN., 1963 REVISED GCT., 1966