APPROVED

ALBOUR COUNTY DEMONUMENTATION

| REMONUMENTATION. For corners in CALHOUN | | Filing Req | Filing Requirement of Act 74, Mich. P.A. 1970 | | ANNE CLE | FEB 4 | | , |
|---|---|------------------------------------|---|----------------|---------------|------------|-------|-----|
| | (County) | Located In: | Corner Code ≠ | | B ≥ 2 × 1 | | | |
| 1. | Public Land Survey | T <u>2S</u> R ∰W T R | | | REGIS NORL | 3/ | 0855 | • |
| | | T R T R | | | | 2 | ¥ .7 | |
| 2. | Property Controlling | S T R | | | 39 F | -E- | | |
| 3. | in Section Miscellaneous Property in Sec. | S T R S T R S T R | | Register of De | eds Stam | p & File | Numb | er |
| 4. | Lot No, R | lecorded Plat | | A R C | DEF | GН | 1 1 6 | |
| 5. | Private Claims | | | 2 6 | - 5 - 4 - | - 3 - 3 | | |
| ı | Michael A Great | t in a field survey on <u>Janu</u> | iary 12, | 3 4 7 | 8 9- | 10- | 11- | 12- |

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Hodgeman 1889 Re-Survey Found stake hole and used

remains of both bearing trees

8" Hickory West 9 1/2° East, 43 lks

4" Hickory North 44°West, 60 1ks


No date of Name

West side of large stone

8" Hickory, SE, 38.0° 8" Elm, N8°E, 26.4'

8" Oak, SW, 39.5'

Noted as gone by D. Dek. 12-14-78



1991 King Ryan and Assoc. Set Iron

8" Oak, N50°W, 135.2' 8" Maple S20°W, 37.1'

8" Maple S30°E, 42.4'

4" Oak, S60°E, 85.2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1991 No evidence of corner or witness trees. Dug in three separate locations and found nothing. Set iron midway on line between I-7 and K-7.

CUENTLY & REMONUMENTATION

OCT 27 1994

COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Berntsen monument and monument box and stamped license # 39079 and corner information in top.

Witnesses:

Nail and spotter in 8" Oak, N50°W, 135.2' Nail and spotter in 8" Maple, S20°W, 37.1' Nail and spotter in 8" Maple, S30°E, 42.2' Nail and spotter in 4" Oak, S60°E, 85.2'

831 LIBER 1730 PAGE

Date

OF MICHIG MICHAEL , GROAT PROFESSIONAL SURVEYOR No. 39079 OFESSIONAN 2-2-94

Euryevor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975**