

CALHOUN COUNTY REMONUNTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners	-in

Property in Sec.

ro	r comers in			
	Calhoun (County)	Located In:	Corner Code ##	
1.	Public Land Survey	T <u>2S</u> R <u>7W</u>	K-5	
		T R		
		T R		
		T R		
2.	Property Controlling	S T R		
	in Section	S T R		STATE OF NICHIGAN
3.	Miscellaneous	S T R		
			·	Register of Deeds Stemp & File Number

____, Recorded Plat _____ 4. Lot No. Private Claims __

MICHAEL A. GROAT, in a field survey on April 2 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Resurvey 1889, Hodgman Found old stake hole Placed tile in hole 16" Oak S67°W 1.17 chains 6" Oak S69°W 1.01 chains

1951 concrete monument over tile 5" Elm, SW, 72.51' 7" Twin Oak, S60°E 72.55' 14" Oak, West 39.2' 4" Iron post, West 36.6'

1975 Pike Iron in monument box 2" twin oak, 73.74' 2" Oak, West 32.2' 4" Iron corner post, Wes

RECORDED

B 22 ARR 94 A:54 A.H.

3

10

11

12

ANNE B. NORLANDER

blekk – regiptek of deed

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron in monument box. Box and iron were cemented in ground. Held this as corner

> SURVITY & REMONUMENTATION

LIBER 1743 PAGE 407

OCT 27 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/2" iron in concrete in monument box.

8' East of centerline of 11 Mile road 2' South of centerline of F Drive North NAIL AND SPOTTER in U.P. S15°E, 77.1'
NAIL AND SPOTTER in 24" Oak, N85°W, 39.2' Stop sign, N45°E, 35.5'

