## SURVEY & REMONUMENTATION

## APPROVED, Date SET 18194 CALHOUN COUNTY

PEMONUMENTATION.

CALHOUN COUNTY REMONUMENTATION

MAR 2 1 1997

## LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN

Calhoun (County)		Located In:	Corner Code ≠≠	CALHOUN COUNTY Recorded				
Eckford Tov	-	- 2 C - E W	0.1	24 SEP 96 11:00 A.M.				
Public Land Su	rvey	T 3 S R 5 W T R T R T R	C-1	ANNE B. NORLANDER CLERK - REGISTER OF DEEDS				
<ol> <li>Property Control in Section</li> <li>Miscellaneous Property in Section</li> </ol>	s s	T R T R T R		Register of Deeds Stamp & File Number				
				A B C D E F G H I J K L				
do hereby certify that in fines 1 and 2 abov current manual of sur Management or by a d above were in conform Court of Law; estable expressed below:  NOTE: Not more to on this cer	under requirement re were in conform vey instructions of lecree of a Court of mance with the rule blished, re-established, than 4 corners, artificate.	ts of P.A. 74, Michigan P.A. on ance with regulations and it the United States Departs Law and/or that the corners of the Michigan Board on shed, monumented, remail in the same town and the sa	September 13 , 19 96 , of 1970, the corner points mentioned drules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a nonumented, recovered, found as drange, may be recorded	4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 - 6 - 18 - 17 - 16 - 15 - 14 - 13 - 7 - 8 - 19 - 20 - 21 - 22 - 23 - 24 - 9 - 10 - 30 - 29 - 28 - 27 - 26 - 25 - 11 - 12 - 31 - 32 - 33 - 34 - 35 - 36 - 13				
A. Description of o Original Gove Lucius Lyon,	ernment Surv	ſ	Vor subsequent restoration: Eckford Township  Corner recorded by Dekeyser & Associates in 1972,  in Liber 1007, Page 67:					
Intersected N West of Post	lorth bounda	ry 59 links	Set corner 38.94' W Marengo Township	est of S.E. Corner, Section 31,				
34" W. Oak 22" D.O.	S5°E S48°W	29 links 40 links	1.65' West of North 0.4' North of fence					
B. Description of c	orner evidence	found and/or method a	pplied in restoring or reestablish	ing corner:				

Found 1/2" iron and witnesses per LCRC, Liber 1007, Page 67.

0.4' North of East and West fence 1.65° West of North and South fence

LIBER 1887 PAGE 980

C.	Description of m	onument for co	orner and acc	cessories e	stablished	to perpetuate locating	the position	of the corner:
F	Replaced 1/2"	iron with	standard	Calhoun	County	${\tt Remonumentation}$	Monument	(Berntsen Monument).
	S.E. Corner,	Section 31,	Marengo	Twp.	East	38.94'	, gri	STATE OF MICHIGANIA
	l8" Maple				North	3.34 <b>'</b>	<u> </u>	2 1
	l2" Elm				South	36.11'		WILLIAM K.
1	.6" Cherry				West	41.72'	3 年 2 年	WILLIAM K.

This is accepted as the best available evidence of the position of the original corner.

29243 SURVENING 29243 ... CAND SURVEY September 18, 1996

SURVEYOR

William K. Crane
Surveyor's Michigan License No.

Date

29243