1993

CALHOUN COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing Requirement of Act 74, Mich. P.A.	1970 🏂 💆
For corners in Calhoun	Located In: Corner Code :##	ACCONSTITUTE OF THE PROPERTY O
1. Public Land	T 4S. R 4W. I-3 T R T R	CORECT ALIVE VALUE ALIVE VALU
 Property Coin Section Miscellaneo Property in Section 	s	Register of Deeds Stamp & File Number
4. Lot No 5. Private Clair	ms	A B C D E F G H I J K L M
do hereby certify in lines 1 and 2 a current manual of Management or b above were in concourt of Law; expressed below	in a field survey on August 4, 19.29. It has under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned above were in conformance with regulations and rules therefore as required in the finite survey instructions of the United States Department of the Interior, Bureau of Larry a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and informance with the rules of the Michigan Board of Land Surveyors or by a Decree of established, re-established, monumented, re-monumented, recovered, found	he nd 7 21 22 23 24 16 a 6 a 6 a 6 a 6 a 6 a 6 a 6 a 6 a 6
NOTE: Not me	ore than 4 corners, all in the same town and range, may be recorded	12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sec. 2,3,10 & 11, Town 4 South, Range 4 West, Homer Twp.

Misc. Calhoun County Surveyor Records (no date or surveyor given): an iron rod and brick; Hickory 8" S. 16° W. 43.2 links.

Spike set by Davis Land Surveying on a survey of property in 1982. This corner was set by measuring lines of occupation North-South-East and West. No witnesses given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found spike as established by Davis Land Surveying, in centerline intersection of gravel roads, and accepted this corner as the best available evidence of the position of the original corner.

No trace of iron rod and brick or 8" Hickory per "A" above, was found by Davis or myself.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced spike set by Davis Land Surveying with a 30" long cast iron Harrison Marker. of Harrison Marker is 6" below gravel road surface). In centerline intersection of 28 Mile Rd. & N Drive S.; S.W. cor. house foundation N. 50° E. 122.20'; N.E. cor. garage (siding) S. 10° W. 120.00'; N.E. cor. concrete slab S. 52° W. 103.5'; P.K. nail in W. side of power pole S. 38° E. 157.30'; center of 20" Butternut of MICHIGAN

> FREDERICK J. **CUTCHER**

SURVEYOR

N. 68° E. 75.20'.

LIBER 1700 PAGE 142

August 23, 1993

Signed by Arederick J. Cutch Surveyor's Michigan License No. 24592

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983