CALHOUN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

APPROVEDA
Date 112 1995
CALHOUN COUNTY
REMONUMENTATION

For anymore in	Filing Requiremen	it of Act 74, Mich. P.A. 19	70 REMONUMENTATION.		
For corners in Locat	ed In:	Corner Code #			
Burlington Twp.					
ग T T	4S R 7W R R R R R R R R R R R R R R R R R	K-9	STATE OF NICHIGAN CALHOUN COUNTY RECORDED		
in Section S T	R R R R		22 SEP 95 10:03 A.N.		
	R		Register of Deed無Stanting 刷更Number		
			CLERK - REGISTER OF DEEDS		
4. Lot No, Recorded Plat			ABCDEFGHIJKL		
5. Private Claims					
			2 - 6 - 1 - 5 - 1 - 3 - 1 - 3 - 1 - 3		
			3		
			4 7 8 9 10 11 12 -		
I, Michael A. Groat, in a field surve	evon July 3	. 19 95	5		
the state of the s					
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current					
manual of survey instructions of the Unite	d States Department of	of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a					
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors of dy a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found					
as expressed below:	ionariou, monamomou, n	, , , , , , , , , , , , , , , , , , , ,	10 30 29 28 27 26 25		
NOTE: Not more than 4 corners, all in th	a come town and rang	e may be recorded			
on this certificate.	e salle town and land	e, may be recorded	12 31 32 33 34 35 36		
			13		
A. Description of original monument a	nd accessories and/o	r subsequent restoration:			
Lyon 1825	A.H.	Chase 1935	Cutcher 1980		
30" Beech N 43°E, 19	Links Found	i stone	Found 3/4" Iron		
11" Beech S 83½ W 42½		concrete monument	Gate Post, N 65°E, 35.6'		
	16" 1	Maple SW 42.1'	U-pole, S 15 W, 83.0'		

16" Maple SW 42.1' 16" Maple S 20°E 99.3'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Iron and measured to Gate post and Utility pole referenced by Cutcher in 1980. Dug but found no remains of stone or concrete monument. Other concrete monuments found in the area had no re-rod in them, it was assumed that the monument was removed for this reason and replaced with the iron. Accepted as a good perpetuation of original monument.

FEB 2 2 1996

LIBER 1822 PAGE 37

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Berntsen monument and monument box in centerline of road, from which

Nail and spotter in Utility pole, S 20°W, 86.4' Nail and spotter in fence post, N 45°W, 51.0'

Nail and spotter in wood fence post, N 40°E, 57.3'

Southerly guard rail post, N 5°E, 174.1



Signed by Michael A. Groat	1. Lust	Date
Michael A. Groat Surveyor's Michigan License No	39079	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 23, 1971 REVISED MAY 14, 1978
		REVISED JAN., 1983