SURVEY & REMONUMENTATION

APPROVED

Date 10-19-94 CALHOUN COUNT REMONUMENTATION

For corners in

4 Lot No 5. Private Claims _

CALHOUN COUNTY REMONUMENTATION

APR 2 6 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

CALHOUN (County)	Located in:	Corner Code ##	
ATHENS TWP 1. Public Land Survey	T <u>4 S</u> R <u>8 W</u> T R T R	F-11	STATE OF MICHIGAN CALHOUN COUNTY RECORDED
Property Controlling in Section Microlleneous	T R S T R S T R S T R		25 OCT 94 9:03 A.M ANNELB. NORLANDER
Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number
4. Lot No	, Recorded Plat		ABCDEFGHLJKL

ROBERT R. CARR , in a field survey on _____SEPTEMBER 8 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

ORIGINAL CORNER SET BY DEPUTY SURVEYOR, ROBERT CLARK, 1826. RE-SURVEY BY COUNTY SURVEYOR, F.A. COURTWRIGHT, 1896. SET POST AT AVERAGE DISTANCE (40.26 CH) ON SOUTH LINE SECTION 28. MAPLE 5" S65-1/2°W 36 LKS; MAPLE 12" N24°W 73 LKS. L.W. CHASE, 1961 MAPLE 20" S60°W 24.10FT. G.F. KARNS 1965 (ROAD COMMISSION) MAPLE 24" S55°W 24.9 FT. MAPLE 24" S55°W 24.9 FT. L.C.R.C. LIBER 1207, PG 14 24" MAPLE \$55°W 24.9 FT 28" OAK DUE EAST 23.5 FT NE CORNER BRICK POST \$35°W 28.6 FT

NE CORNER BRICK POST SO5°E 23.9 FT. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON OVER 1/2" PIPE MATCHING WITNESSES FORM L.C.R.C. LIBER 1207 PG 14. ALSO FOUND 30" MAPLE S62°W 23.7 FT TO CENTER WHICH APPEARS TO BE BEARING TREE (5" MAPLE) FROM RE-SURVEY. DUG 3'X3'X4' HOLE & FOUND NO OTHER EVIDENCE OF CORNER. ACCEPTED IRON OVER THE AS PERPETUATION OF CORNER.

LTRER 1773 PAGE 886

8

10

11

12

C. Description of monument for co	and accessories established to perpetuate locating the position of the co	orner:
-----------------------------------	---	--------

BERNTSEN MONUMENT. NAIL & SPOTTER IN NLY SIDE 30" MAPLE S62°W 23.71 FT.
NAIL & SPOTTER IN NELY SIDE 36" MAPLE N65°W 83.44 FT.
NAIL & SPOTTER IN SWLY SIDE 48" OAK S70°E 22.54 FT.

NAIL & SPOTTER IN ELY SIDE 16" OAK N13°E 57.43 FT.

20.5 FT SLY OF CENTERLINE ROAD

NE CORNER BRICK PILLAR SO5°E 23.67 FT.

NE CORNER BRICK PILLAR \$37°W 28.50 FT.



Signed by	VI.
ROBERT R. CARR Surveyor's Michigan License No.	20704