Liber 00003 Page 00004

LAND CORNER RECORDATION CERTIFICATE

Fo	or corners in Marcellus To	Filing Requir	rement of Act 74, Mic	h. P.A. 1970	TATE OF MICHIGAN DUNTY OF CASS	27g	
		Located In:	Corner Code ##		ecorded n_17_1995 ng*n5*70		
1.	Public Land Survey	T <u>55</u> R13W T R	A-1	Ĥr	0-13-1995 09:05:30 nn L. Simmons		
2.		T R T R		RI	EGISTER OF DEEDS	Raiffied by In Accordat	
3.	Miscellaneous S	T R _ T R		Reg	ister of Deeds Stamp 8		
	Lot No, Recorded				A B C D E F C	3 H I J K L M	
	Donald R. Gilchrist	D.	ecember 26,	94	4 7 8 9	-10-11-12	
in cu Ma ab Co	hereby certify that under requirements lines 1 and 2 above were in conforma rrent manual of survey instructions of the tragement or by a decree of a Court of Libove were in conformance with the rules purt of Law; established, re-established becased below:	6 -18 -17 -16 - 7 - 8 -19 - 20 - 21 - 9 - 10 - 30 - 29 - 28 - 10 - 20 - 21 - 10 - 20 - 21 - 21 - 20 - 21 - 21	22 23 24				
NC	OTE: Not more than 4 corners, all on this certificate.	in the same town ar	nd range, may be record	ied	11 32 33 33 13	34 35 36	
A.	Description of original monument 1827 - William Brook Set Post		d/or subsequent restora	tion:		199 6	
	1915 - W.H. Goss, C. Found Stor		fence to South	h.	COMMIS	SION	
<pre>11/16/81 - J.C. Hunt, R.L.S., Section 6, Marcellus Township, found corner. Distance East to quarter post = 2168.40' (Gov't = 2166.12) North quarer post to Northeast Corner = 2631.40'. Distance South to quarter post = 2173.22' (Gov't = 2172.06')</pre> B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:							
	Found iron rod with illegible cap in 1" dia. pipe. Removed iron and pipe and found 5/8" iron rod. Removed iron rod and excavated to a depth of 5', then used prod to check an additional 2' deep for a total of 7' below surface, found nothing. 5/8" iron rod was approved and authorized by the Cass County Remonumentation Peer Group on August 24, 1995 and is accepted as a careful & faithful reestablishment of the original corner.						

■C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 5/8" iron. Removed iron and placed standard Van Buren County Section Corner Monument and Mon. box over, Accessories:

Nail & Tab in wood grape vine fence post #187, North 62.52' Nail & Tab in Utility Pole S.70°E., 121.91' Nail & Tab in Utility Pole S.15°W., 26.71' Nail & Tab in Utility Pole S.60°W. 53.76'

In line with tree row to South and fence to North.

-igned by $_{\it A}$ Date urveyor's Michigan License No. Donald R. Gilchrist, RLS #13583

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975