Ratified by Feat Group	
In Ascerdance With PA 313 Chairman 100 LAND CORNER RECORDATION CERT	TEICATE
Date 24, 1995 Filing Requirement of Act 74, Mich. P	A. 1970STATE OF MICHIGAN
CASS COUNTY REMONUMENTATION CASS Located In: Corner Code ##	
(County)	12-04-1995 11:53:24
1. Public Land Survey T 5 R 13 B-1 T R R	
T R	Arm L. Simmons REGISTER OF DEEDS
T R	
in Section S T R	Liber 00003 Page 0020 Register of Deeds Stamp & File Number
Property in Sec. S T R	negister of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	2 6 5 7 3 7 2 7 1 -
	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Dale L. Kesler, in a field survey on December 9, 19 94	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention lines 1 and 2 above were in conformance with regulations and rules therefore as required in current manual of survey instructions of the United States Department of the Interior, Bureau of	in the 18-1-17-16-15-14-1-13-
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree	and 5 8 19 20 21 22 23 24
Court of Law; established, re-established, monumented, re-monumented, recovered, four expressed below:	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	11
on this certificate.	12 31 32 33 34 35 36 13
A. Description of original monument and accessories and/or subsequent restoration	:
This conner was not set by the Government	
April 1871 - Established by J. C. Bradt, County Surveyor 4" Oak - South 2° West - 51 Links 20" White Oak - South 69 3/4° East - 2.31 1/2 Link	
Dec. 1897 - F. E. Smith - County Surveyor - Established a 14" White Oak - North 62 1/3° West - 260 Links	nd set stone over post -
B. Description of corner evidence found and/or method applied in restoring or reesta	ablishing corner:
Found 1" iron pipe. Distances to adjacent corners consistent. Accepted iron as best evidence of cor	
	MAR 2 7 1996
	COMMISSION
Description of monument for corner and accessories established to perpetuate loc	cating the position of the corner:
Set 3/4" iron pipe with aluminum cap in monument box in pipe and is accepted as a careful and faithful perpetuate original corner.	n place of found l" iron
Set nail w/washer in 8" Oak - N. 20° W 36.30' Set nail w/washer in 10" Twin Hackberry - S. 45° W Set nail w/washer in 8" Cherry - N. 3° W 38.50' Set nail w/washer in 10" Hackberry - S. 45° E 40 Centerline East & West Road is 1.00' South	DALEL VESLER KESLER LAND SURVEYOR *
ingred by Dale (Kall Date)	Occupant 1995 OLAND SURFERENCE STATE OF THE PERSON OF THE
urveyor's Michigan License No. 38117	- ASBECRETO.

FDAM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983